

Basic Condition Guide

•	Report ID: 27,865,029		Version: 2	
	Created:	30 Dec 2025		

	ОК	Requires Attention	N/A
Engine			,
Oil level	/		
Smoke & fumes	V		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise		~	
Clutch			'
CV joints	✓		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		2	2.0 mm
Right front		3	3.0 mm
Left rear		4	1.5 mm
Right rear		5	5.0 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	✓		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	•		
Window winder FR	/		
Window winder RL	/		
Window winder RR	✓		
Rear view mirrors		•	
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	1		
Reversing camera	/		


Make:	Suzuki	Model:	Baleno
Body Style:	Hatchback	Year:	2017
Rego No.:	KHT589	Rego Expiry:	13 Feb 2026
WoF Expiry:	26 Feb 2026	Odometer:	124,446 Kms
Good No.:	27865029	VIN:	MA3EWB52S00272592
Next Service:	131,703	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Headlights yellowing. Stone chips in windscreen. Paint worn in drivers door sill

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Right mirror not adjusting horizontally. Key blades not secure in key fobs Transmission whine under load

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Samuel Weir		
Published by:	David Duke		
Inspection Date:	18 Dec 2025		

I have read and understood
this condition guide:

NAME			