

| Report ID: | 27,865,086 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 31 Dec 2025 | | |


Requires

| Make: | Ford | Model: | Courier |
|---------------|-------------|------------------|-------------------|
| Body Style: | Utility | Year: | 1999 |
| Rego No.: | QGB46 | Rego Expiry: | 07 Nov 2024 |
| WoF Expiry: | 15 Jun 2026 | Odometer: | 205,268 Kms |
| Good No.: | 27865086 | VIN: | MNABSCE40XW111761 |
| Next Service: | | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

| Key | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Rear seats don't lift up so can't see if Jack equipment present

| Conditions During Body Inspection Dry | Under Carriage and Under Bonnet Inspection Comments | | |
|---------------------------------------|---|-----|--|
| | Conditions During Body Inspection | Dry | |

Brake travel minimal before brakes are on, nothing obvious other than the brake bias valve is almost impossible to move. Coolant overfilled

| Interior Comments | |
|-------------------|----------------------|
| Seats: marks | |
| Carpets: | hole driver footwell |
| Panels: | Average |
| Dashboard: | Average |

General Comments

Air conditioning and heating systems ok. Radio requires code

| Road Conditions During Test Drive | | Dry | | |
|-----------------------------------|---------------|---------|-------------|-----|
| Engine Timing Mechanism | | Cambelt | | |
| Evidence of Cam Belt Replacement | | Yes | V No | Kms |
| Inspected by: | Gary Adams | | | |
| Published by: | Anna Zandstra | | | |
| Inspection Date: | 18 Dec 2025 | | | |

| | | Radio (ba |
|----------------------------------|------------|------------|
| ditions During Test Drive | Dry | CD (basic |
| ming Mechanism | Cambelt | Number |
| of Cam Belt Replacement | Yes No Kms | Central le |
| by: Gary Adams | | Remote |
| d by: Anna Zandstra | | Sat. nav. |
| Date: 18 Dec 2025 | | Reversin |
| and understood on guide: NAME | | SIGNATURE |

| | | OK | Attention | N | I/A |
|---|--------------------------------|--------------|-----------|-----|----------|
| | Engine | | | | |
| | Oil level | / | | | |
| | Smoke & fumes | / | | | |
| | Engine performance | ✓ | | | |
| | Noise | / | | | |
| | Coolant condition | <i>V V V</i> | | | |
| | Cooling performance | ~ | | | |
| | Radiator / Hoses (visual) | / | | | |
| | Transmission | | | | |
| | Operation | / | | | |
| | Noise | / | | | |
| | Clutch | <i>V V</i> | | | |
| | CV joints | / | | | |
| _ | Wheel bearings | / | | | |
| | Brakes | | | | |
| | Performance | | ~ | Π | |
| _ | Hand brake | / | | | |
| | Tyres (lowest observed tread d | epth of | tyres) | | |
| | Left front | | | 5.0 | mn |
| | Right front | | (| 6.0 | mn |
| | Left rear | | į | 5.0 | mn |
| _ | Right rear | | | 5.0 | mm |
| | Spare | Yes | | | |
| | Suspension | | | | |
| _ | Suspension performance | ~ | | | |
| | Steering performance | | • | | |
| | Shock absorbers | / | | | |
| | Air Conditioning / Heater | | | | |
| | Operation | ~ | | | |
| | Electrical / Accessories | | | | |
| | Head lights | ~ | | | |
| | Tail lights | / | | | |
| | Indicators | ~ | | | |
| | Dashboard warning lights | / | | | |
| | Wipers (front & rear) | V V | | | |
| | Window winder FL | ✓ | | | |
| | Window winder FR | ✓ | | | |
| | Window winder RL | | | | / |
| | Window winder RR | | | | ~ |
| | Rear view mirrors | ✓ | | | |
| | Radio (basic test only) | | / | | |
| | CD (basic test only) | | | | / |
| | Number of keys | 2 | | | |
| | Central locking | ✓ | | | |
| | Remote locking | | | | / |
| | Sat. nav. (basic test only) | | | | <u> </u> |
| | Reversing camera | | | T | / |
| | | | | | |

| ı | have read and | d understood |
|----|---------------|--------------|
| tŀ | nis condition | auide: |