


•	Report ID:	27,866,783	Version:	2
	Created:	31 Dec 2025		

Make:	Holden	Model:	Cruze
Body Style:	Sedan	Year:	2015
Rego No.:	JKL303	Rego Expiry:	04 Jan 2026
WoF Expiry:	15 Nov 2026	Odometer:	142,296 Kms
Good No.:	27866783	VIN:	6G1PE5EM4FL143528
Next Service:	135,000	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Dents in left sill

Stone chips in windscreen

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

Battery doesn't fit

Oil seepage, evidence of coolant leak

RF tyre inner shoulder worn

Left rear shock absorber leaking

=g				
Interior Comments				
Seats:	Average			
Carpets:	Average			
Panels:	Average			
Dashboard:	Average			
General Comments				

# 2/3 key remote buttons broken

this condition guide:

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
Inspected by:	ted by: Samuel Weir			
Published by:	shed by: Andrew Totton			
Inspection Date:	31 Dec 2025			

I have read and understood		
this condition guide:	NAME	

	ОК	Requires Attention	N/A
Engine	OK	Attention	13/73
Oil level			
Smoke & fumes	<b>/</b>		
Engine performance	<b>/</b>		
Noise	<b>V</b>		
Coolant condition	~		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)		<b>/</b>	
Transmission			
Operation	<b>✓</b>		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		3	3.0 mm
Right front		3	3.5 mm
Left rear		5	5.5 mm
Right rear		7	7.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	<b>/</b>		
Shock absorbers		<b>/</b>	
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>✓</b>		
Tail lights	<b>/</b>		
Indicators	<b>/</b>		
Dashboard warning lights	/		
Wipers (front & rear)	<b>/</b>		
Window winder FL	/		
Window winder FR	<b>/</b>		
Window winder RL	<b>/</b>		
Window winder RR	V V V		
Rear view mirrors	<b>/</b>		
Radio (basic test only)	<b>/</b>		
CD (basic test only)	<b>/</b>		
Number of keys	3		
Central locking	<b>✓</b>		
Remote locking	<b>✓</b>		
Sat. nav. (basic test only)	<b>/</b>		
Reversing camera	<b>✓</b>		

SIGNATURE		