

Report ID: 27		27,867,066	Version:	3
	Created:	03 Jan 2026		

OT.	Turners Basic Condition Guide			Report ID: 27
				Created: 03
Make:	Ford	Model:	Ecosport	
Body Style:	SUV	Year:	2017	
Rego No.:	RLS197	Rego Expiry:	24 Sep 2026	Engine
WoF Expiry:	15 Dec 2026	Odometer:	68,966 Kms	Oil level
Good No.:	27867066	VIN:	MAJBXXMRKBGS78648	Smoke & fume
Next Service:	79000	Service History:	No	Engine perform
		Service History.	110	Noise
Note: This report is This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condi
diagnostic testing ur full mechanical insp	ndertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/l d this can be arranged f	h from cold. The Vendor recommends a or an additional charge.	Cooling perfor
Key			,	Radiator / Hose
•	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	Transmission
D = Dent P	T = Paint defect P = Paint defect	in dent SC = Sto	ne Chips	Operation
				Noise
		\Box		Clutch
				CV joints
	THE WIT			Wheel bearing
b				Brakes
	Performance			
	Hand brake			
sc	Tyres (lowest o			
				Left front
			(Q)	Right front
				Left rear
	W	D SD	S	Right rear
Note: some defects	and blemishes may not be	displayed in the diagra	am	Spare
	on Comments			Suspension
Undertray miss	ing			Suspension pe
				Steering perfo
				Shock absorbe
Conditions Du	ring Body Inspection		Dry	Air Condition
	ge and Under Bonnet	Inspection Comm	· ·	Operation
	<u> </u>	·		Electrical / Ac
				Head lights
				Tail lights
Interior Comn	nents			Indicators
Seats:	Good			Dashboard wa
Carpets:	Good			Wipers (front &
cui pets.	1000			Wipers (Horite

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	V V		
Noise	~		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		6.0 mm
Right front			4 mm
Left rear		(6.0 mm
Right rear		6	6.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	·		
Window winder FR	/		
Window winder RL	·		
Window winder RR	·		
Rear view mirrors	· ·		
Radio (basic test only)	· /		
CD (basic test only)	-		
Number of keys	1	I.	
Central locking	/		
Remote locking	<u> </u>		
Sat. nav. (basic test only)	-		·
Reversing camera			
neversing currier		ļ	

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Greg Morgan			
Published by:	Bailey Seymour		·	
Inspection Date	18 Dec 2025	-		

I have read and understood this condition guide:

Good

Good

Panels: Dashboard:

General Comments

NAME _

SIGNATURE