

Report ID:	27,867,992	Version:	1
Created:	22 Dec 2025		

Basic Condition Guide			
Make:	Toyota	Model:	Aqua
Body Style:	Hatchback	Year:	2015
Rego No.:	QEN353	Rego Expiry:	26 Mar 2026
WoF Expiry:	04 Sep 2026	Odometer:	54,809 Kms
Good No.:	27867992	VIN:	7AT0H65YX23428479
Next Service:	24/1/26 or 57000km	Service History:	No
liagnostic testing ur	only. Consideration is mad	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
•	= Rust	irack * = Deca	ls W = Significant scuffs
	$\Gamma = Paint defect P = P$		3
		S	S
			PT
	MA UT		
SC 6			
s sc	18		
			S
	\angle		
		<u>s</u>	S
lote: some defects	and blemishes may not be	displayed in the diagra	am
Body Inspecti	on Comments		
Conditions Du	ring Body Inspection		Dry
Under Carriag	e and Under Bonnet	Inspection Comm	nents
Interior Comn	nents		
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
General Comr	nents		
Vehicle drove w	rell.		

		Requires	
	OK	Attention	N/A
Engine			<u> </u>
Oil level	•		
Smoke & fumes	•		
Engine performance	•		
Noise	•		
Coolant condition	•		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission	1	,	
Operation	/		
Noise	•		
Clutch			
CV joints	•		
Wheel bearings	'		
Brakes			
Performance	•		
Hand brake	'		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4 mm
Right front			4 mm
Left rear			4 mm
Right rear			4 mm
Spare	Yes		
Suspension			
Suspension performance	'		
Steering performance	'		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	1		
Indicators	•		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	2		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			
Reversing camera	1		
J. 2011.2.2		<u>I</u>	

,
I have read and understood
this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 22 Dec 2025

Aaron Johnson

Aaron Johnson

Engine Timing Mechanism

Inspected by:

Published by:

NAME			

No

Dry

Timing Chain

Yes

SI	GN	AT	URF	

Kms