

## Basic Condition Guida

•	Report ID:	27,868,949	Version:	1
	Created:	19 Dec 2025		

Make	Ford	Model:	Pangar			Requires		
Make:			Ranger 2011		OK	Attention	N/A	
Body Style:	Utility GCG823	Year:	_	Engine				
Rego No.:	24 Feb 2026	Rego Expiry:	08 Sep 2026	Oil level				
WoF Expiry:	27868949	Odometer:	299,453 Kms MNAUS2E90BW954276	Smoke & fumes	/			
Good No.:	27868949	VIN:	No	Engine performance				
Next Service:		Service History:	Noise					
ote: This report is nis report is a quide	•	e for age and mileage. F	Coolant condition		<b>/</b>			
agnostic testing ur II mechanical insp	ndertaken. The vehicle has b ection prior to purchase an	peen driven up to 50km, ad this can be arranged	Parts have not been dismantled or Van from cold. The Vendor recommends a for an additional charge.	Cooling performance	/			
ey				Radiator / Hoses (visual)	<b>/</b>			
•	= Rust C = C	Crack *= Deca	als W = Significant scuffs	Transmission				
= Dent P	$\Gamma = Paint defect  P = P$	Pin dent SC = Sto	one Chips	Operation	<b>/</b>			
		S SSC		Noise	<b>/</b>			
-		3 330		Clutch	<b>/</b>			
				CV joints	/			
0.DT.00				Wheel bearings				
S PT SC				Brakes				
	MC II			Performance	V			
			sc	Hand brake	V			
sc	18			Tyres (lowest observed tread depth of tyres)				
				Left front		3	3.3 m	
			(Q)	Right front		3	3.6 mr	
				Left rear			2.7 mr	
		sc	Right rear			4.4 mr		
ote: some defects	and blemishes may not be	e displayed in the diagr	am	Spare	Yes			
	on Comments	. , , , ,		Suspension				
Minor stonechip	os/cracks on windscre	een		Suspension performance	V			
				Steering performance	1			
				Shock absorbers	1			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater		1		
	e and Under Bonnet	t Inspection Comr	Operation	·				
our wheel driv	e	·	Electrical / Accessories		1			
Both front CV b	oots leaking		Head lights		·			
				Tail lights				
Interior Comn	nents			Indicators	1			
Seats:	Good			Dashboard warning lights	1			
Carpets: Good			Wipers (front & rear)	1				
Panels:	Good		Window winder FL	1				
Dashboard:	Good		Window winder FR	1				
General Comr			Window winder RL			1		
	also has rusty water	in radiator	Window winder RR			~		
0 ,	light not working		Rear view mirrors	1				
Both fog light no D player not w	-			Radio (basic test only)	1			
	ns During Test Drive	Dry		CD (basic test only)		·		
		Cambelt			1			
<b>Engine Timing</b>	Mechanism	Campeit		Number of keys	1			

I have read and understood this condition guide:

Inspection Date: 18 Dec 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Janine Bell

Cameron Senior-Arnold

NAME

Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

Kms