

Report ID:	27,869,095	Version:	2
Created:	22 Dec 2025		

		Posi	c Condition Guide	Report
	nue	<u>Dasi</u>	C Condition Guide	Created
Make:	Holden	Model:	Captiva 7	
Body Style:	SUV	Year:	2017	For arise of
Rego No.:	KWH256	Rego Expiry:	01 Nov 2025	Engine
WoF Expiry:	11 Sep 2026	Odometer:	138,164 Kms	Oil leve
Good No.:	27869095	VIN:	KL3CD2669JB003923	Smoke
Next Service:	145,801kms	Service History:	No	Engine
Note: This report is	not a warranty			Noise
			arts have not been dismantled or n from cold. The Vendor recommends a	Coolant
	ection prior to purchase an			Cooling
Кеу				Radiato
	$= Rust \qquad C = C$			Transm
D = Dent P	T = Paint defect P = P	in dent SC = Stor	ne Cnips	Operati
		P	SP	Noise
				Clutch
	\sim		SSC	CV joint
SC (<u> </u>		Wheel k
-				Brakes
1		$\parallel \parallel \parallel \perp$		Perform
P SC	R			Tyres (lo
				Left from
			(Q)	Right fro
				Left rea
		P		Right re
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare
	ion Comments			Suspen
				Suspen
				Steering
				Shock a
Conditions Du	ring Body Inspection		Dry	Air Con
Under Carria	ge and Under Bonnet	Inspection Comm	ents	Operati
Oil leaks.				Electric
				Head lig
				Tail ligh
Interior Comr	nents			Indicato
Seats:	Average			Dashbo
Carpets:	Average			Wipers
Panels:	Average			Windov

		Requires	
	OK	Attention	N/A
Engine			1
Oil level	/		
Smoke & fumes	•		
Engine performance	•		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission	I .	ı	
Operation	/		ļ
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front			5.5 mm
Right front			6.5 mm
Left rear		(6.5 mm
Right rear		6	6.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			
Head lights	/		
Tail lights	1		
Indicators	/		
Dashboard warning lights	1		
Wipers (front & rear)		~	
Window winder FL	/		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	1		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			
Reversing camera	1		
		<u> </u>	

Interior Comm	ents	
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Rear	Diff	binding

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	LukaAjitvan Woer	den
Published by:	Cody O'Neill	
Inspection Date:	19 Dec 2025	

have read and understood
this condition guide:

NAME			

SIGNATURE	