

•	Report ID:	27,870,388	Version:	1	
	Created:	23 Dec 2025			

OK

Requires Attention

N/A

		Dos:	a Canalitian Cuida	Report ID:	27,870,388
	nue	S Basi	c Condition Guide	Created:	23 Dec 20
Make:	Ssangyong	Model:	Rexton		
Body Style:	SUV	Year:	2013	Engine	
Rego No.:	GRM450	Rego Expiry:	09 Jul 2026	Oil level	
WoF Expiry:	_		250,131 Kms	Smoke & fumes	
Good No.:	od No.: 27870388 VIN: KPTH0C1FSCP314232		KPTH0C1FSCP314232	Engine performance	
Next Service:	lext Service: Due Service History: No				
Note: This report is This report is a guide	Coolant condition				
diagnostic testing un		een driven up to 50km/l	n from cold. The Vendor recommends a	Cooling pe	rformance
Key		a and can be an angea .		Radiator / I	Hoses (visual)
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmiss	ion
D = Dent P	Γ = Paint defect P = Pi	in dent SC = Sto	3	Operation	
SSC		D SC S R SC W		Noise	
330	Clutch				
			S D SC W	CV joints	
	MA UT		020011	Wheel bea	rings
S SC W				Brakes	
	$M \subset \mathbb{N}$			Doufoussas	

S D SC

S SC

Note: some defects and blemishes may not be displayed in the diagram

S SC

S SC

Body Inspection Comments

S SC

S SC

Cond	itions Duri	ng Body Inspection	Dry					
Unde	Under Carriage and Under Bonnet Inspection Comments							
Steerii Engine	Drive belt making noise Steering rack misting Engine oil leak Transmission leak oil							
Inter	Interior Comments							
Seats	:	Average						
Carpe	ets:	Average						
Panel	s:	Average						
Dash	Dashboard: Average							
Gene	General Comments							
LH dip AC no	Airbag light on LH dipped beam not working AC not working Remote key damaged							
Road	Condition	s During Test Drive	Dry					
Engir	e Timing <i>I</i>	Mechanism	Timing Chain					
Evide	Evidence of Cam Belt Replacement		Yes	No	Kms			
Inspe	Inspected by: Bobby Zhong							
Publi	Published by: Bobby Zhong							
Inspe	Inspection Date: 23 Dec 2025							

Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			'
CV joints	1		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread o	lepth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear			6 mm
Right rear			6 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation		/	
Electrical / Accessories			
Head lights		'	
Tail lights	~		
Indicators	/		
Dashboard warning lights		'	
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors		'	
Radio (basic test only)	/		
CD (basic test only)	~		
Number of keys	1		
Central locking	/		
Remote locking	/	ļ	
Sat. nav. (basic test only)			'
Reversing camera			

۱ŀ	าลง	vе	rea	d a	and	u	nd	ers	sto	od
th	nis	co	nd	itic	n g	ju	ide	2:		

N	Δ	M	E

SIGNATURE