

Basic Condition Guide

•	Report ID: 27,871,122		Version:	1
	Created:	19 Dec 2025		

	umei	S Dasi	C Condition Guide	Created:	19 Dec 2025			
Make:	Suboru	Model:	Logopy			1	Requires	
	Subaru	Year:	Legacy 2009			ОК	Attention	N/A
Body Style:	Wagon		09 Jun 2026	Engine		1		
Rego No.: LNC230		Rego Expiry:	-	Oil level		/		
WoF Expiry:	17 Dec 2026	Odometer:	181,301 Kms	Smoke & fu	imes	~		
Good No.:	27871122	VIN:	7AT0GF0BX18172721	Engine per	formance	1		
Next Service:	160,100kms	Service History:	INO	Noise		1		
Note: This report is This report is a guide	only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	ndition	1		
diagnostic testing un	dertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/l	n from cold. The Vendor recommends a	Cooling pe	rformance	1		
Key			-	Radiator / I	Hoses (visual)	1		
-	= Rust C = C	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion			
D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation		/		
S P D S D						/		
S P D S D								V
	(A)		SDPT	CV joints		/		
				Wheel bea	rings	/		
PT SC				Brakes				
				Performan	ce	1		
				Hand brake	2	1		
S D PT SC	18			Tyres (lowest observed tread depth of tyres)				
				Left front			4	4.5 mm
			(Q)	Right front				5 mm
				Left rear		5 mr		
	<u>s</u>	D D	S P	Right rear		5.5 mm		
Note: some defects a	and blemishes may not be	e displayed in the diagra	nm	Spare		Yes		
Body Inspection	on Comments			Suspensio	n			
	housing cracked.			Suspension	n performance	~		
Right rain guard	l broken.			Steering pe	erformance	~		
				Shock abso	orbers	1		
Conditions Dur	ing Body Inspection		Dry	Air Conditioning / Heater				
Under Carriag	e and Under Bonnet	Inspection Comm	nents	Operation		/		
				Electrical /	Accessories		<u> </u>	
				Head lights	5	~		
				Tail lights		~		
Interior Comm	nents			Indicators		1		
Seats:	Poor			Dashboard	warning lights	1	İ	
Carpets:	Poor			Wipers (fro	nt & rear)		~	
Panels:	Poor			Window w	inder FL	1		
Dashboard: Poor				Window w	inder FR	1		
General Comments					inder RL	1		
Radio turns on but plays no sound.				Window w	inder RR	1		
Rear wiper needs replacing. Radio not mounted.				Rear view r	mirrors	1		
Radio not moun				Radio (basi	c test only)			
Road Conditions During Test Drive Dry					est only)		1	1
		Cambelt		Number of	•	1	1	

I have read and understood this condition guide:

Inspection Date: 19 Dec 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

LukaAjitvan Woerden

LukaAjitvan Woerden

NAME			

✓ No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Yes

SIGNATURE		

1