

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,871,244 | Version: | 2 |
| Created: | 24 Dec 2025 | | |


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Suzuki | Model: | Swift |
| Body Style: | Hatchback | Year: | 2010 |
| Rego No.: | MUM87 | Rego Expiry: | 13 Nov 2026 |
| WoF Expiry: | 06 Jan 2027 | Odometer: | 137,742 Kms |
| Good No.: | 27871244 | VIN: | 7AT0GK0CX20573866 |
| Next Service: | 143470 kms | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

All tyres dry cracking.

Conditions During Body Inspection

Wet

Under Carriage and Under Bonnet Inspection Comments

Front CV axle inner boots grease leaks.

Front lower control arm ball joints grease leaks.

Interior Comments

| | |
|------------|------|
| Seats: | Good |
| Carpets: | Good |
| Panels: | Good |
| Dashboard: | Good |

General Comments

W/S stone chip in and out CVA.

Clock display not working.

| | |
|-----------------------------------|--|
| Road Conditions During Test Drive | Wet |
| Engine Timing Mechanism | Timing Chain |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by: | Eleoit Kumar |
| Published by: | Sam Huang |
| Inspection Date: | 19 Dec 2025 |

| | OK | Requires Attention | N/A |
|---|----|--------------------|--------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 4.0 mm |
| Right front | | | 5.0 mm |
| Left rear | | | 6.0 mm |
| Right rear | | | 6.0 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____