

## **Basic Condition Guide**

| • | Report ID: | 27,872,555  | Version: | 1 |
|---|------------|-------------|----------|---|
|   | Created:   | 20 Dec 2025 |          |   |

|   | Dillei                                     |                                    |  | Created:                                     | 20 Dec 2025      |          |           |          |  |
|---|--|------------------------------------|--|--|------------------|----------|-----------|----------|--|
| Make:   | Mazda                                      | Model:                             | Demio  |  |                  |          | Requires  |          |  |
| Body Style:   | Hatchback                                  | Year:                              | 2005   |  |                  | OK       | Attention | N/A      |  |
| Rego No.:   | LZY44                                      | Rego Expiry:                       | 20 May 2026  | Engine                                       |                  |          |           | l e      |  |
| WoF Expiry:   | 10 May 2026                                | Odometer:                          | 144,445 Kms  | Oil level                                    |                  | <i>'</i> |           |          |  |
| Good No.:   | 27872555 VIN: 7AT0C12HX18420594            |                                    | Smoke & fumes  |  | /                |          |           |          |  |
| Next Service:   |  |                                    |  | Engine performance                           |                  | <i>\</i> |           |          |  |
| Note: This report is  | ,  | Noise                              |  | <i>'</i>                                     |                  |          |           |          |  |
| This report is a guide  | only. Consideration is mad                 |                                    | arts have not been dismantled or<br>h from cold. The Vendor recommends a | Coolant co                                   |                  | <b>/</b> |           |          |  |
| full mechanical insp  | ection prior to purchase ar                | - 31                               | erformance   | <b>/</b>                                     |                  |          |           |          |  |
| Key   | '  | ,                                  |  | Radiator / Hoses (visual)                    |                  |          |           |          |  |
|   | = Rust $C=0$                               | Crack *= Deca<br>Pin dent SC = Sto |  | Transmiss                                    | sion             | l .      |           | <u> </u> |  |
| D = Dent P  | T = Paint defect P = F                     | Operation 🗸                        |  |  |                  |          |           |          |  |
|   |  |                                    |  | Noise  |                  | ~        |           |          |  |
|   |  | T                                  |  | Clutch                                       |                  |          |           | ~        |  |
|   | - 100-                                     |                                    | SC   | CV joints                                    |                  | ~        |           |          |  |
| SC  |  |                                    |  | Wheel bearings 🗸                             |                  |          |           |          |  |
| H   |  |                                    |  | Brakes                                       |                  |          |           |          |  |
| $\mathcal{H}$   |  |                                    |  | Performan                                    | ice              | ~        |           |          |  |
| \   |  |                                    |  | Hand brak                                    | e                | ~        |           |          |  |
| SC  |  |                                    |  | Tyres (lowest observed tread depth of tyres) |                  |          |           |          |  |
|   |  |                                    |  | Left front 3.5 mm                            |                  |          |           |          |  |
|   |  |                                    |  | Right front 4 mm                             |                  |          |           |          |  |
|   |  |                                    |  | Left rear                                    |                  | 3 mm     |           |          |  |
|   | <u>s</u>                                   | P P                                |  | Right rear                                   |                  | 6 mm     |           |          |  |
| Note: some defects  | and blemishes may not b                    | e displayed in the diagra          | am   | Spare  |                  | Yes      |           |          |  |
| Body Inspecti   | on Comments                                |                                    |  | Suspension                                   | on               |          |           |          |  |
|   |  |                                    |  | Suspensio                                    | n performance    | <b>/</b> |           |          |  |
|   |  |                                    |  | Steering p                                   | erformance       | <b>/</b> |           |          |  |
|   |  |                                    |  | Shock abs                                    | orbers           | ~        |           |          |  |
| Conditions Du   | ring Body Inspection                       |                                    | Dry  | Air Conditioning / Heater                    |                  |          |           |          |  |
| Under Carriag   | e and Under Bonne                          | t Inspection Comm                  | Operation  |  | 1                |          |           |          |  |
|   |  |                                    |  | Electrical                                   | / Accessories    |          |           |          |  |
|   |  |                                    |  | Head light                                   | S                | V        |           |          |  |
|   |  |                                    |  | Tail lights                                  |                  | ~        |           |          |  |
| Interior Comn   | nents                                      |                                    |  | Indicators                                   |                  | 1        |           |          |  |
| Seats:  | Good                                       |                                    |  | Dashboard                                    | d warning lights | 1        |           |          |  |
| Carpets:  | Good                                       |                                    | Wipers (fro  | ont & rear)                                  | 1                |          |           |          |  |
| Panels:   | anels: Good                                |                                    |  |  | rinder FL        | 1        |           |          |  |
| Dashboard: Good   |  |                                    |  |  | vinder FR        | V        |           |          |  |
| General Comr  | nents                                      | Window w                           | vinder RL  |  | <b>/</b>         |          |           |          |  |
| Radio not worki   |  | Window w                           | vinder RR  | 1  |                  |          |           |          |  |
|   | t adjusting or retractir                   | ng.                                | Rear view  | mirrors                                      |                  | <b>V</b> |           |          |  |
| Left rear window<br>Clock spring fai  | v not working.<br>I, indicators don't retu | ırn to centre.                     |  | Radio (bas                                   | ic test only)    |          | ~         |          |  |
|   | ns During Test Drive                       | CD (basic t                        | , , , , , , , , , , , , , , , , , , ,                                    |  | V                |          |           |          |  |
| Road Conditions During Test Drive Dry  Engine Timing Mechanism Timing Chain |  |                                    |  |  | f keys           | 2        |           |          |  |
| Evidence of Cam Belt Replacement Yes No Kms                                 |  |                                    |  |  | king             | 1        |           |          |  |
| Inspected by: LukaAjitvan Woerden   |  |                                    |  |  | cking            |          | <b>/</b>  |          |  |

I have read and understood this condition guide:

Inspection Date: 20 Dec 2025

LukaAjitvan Woerden

Published by:

NAME

SIGNATURE

Sat. nav. (basic test only)

Reversing camera