

## **Basic Condition Guide**

Report ID:	27,874,252	Version:	1
Created:	28 Dec 2025		

N/A

3.8 mm 3.8 mm 4.0 mm 5.1 mm

U	ntuet	S Basi	c Condition Guide	Created: 28 Dec 2025		
Make:	Mitsubishi	Model:	ASX			Requires
Body Style:	SUV	Year:	2017	Engine	OK	Attention
Rego No.:	LCB570	Rego Expiry:	04 Oct 2025	Oil level	V	
WoF Expiry:	21 Feb 2026	Odometer:	151,188 Kms	Smoke & fumes	1	
Good No.:	27874252	VIN:	JMFXTGA2WJZ004446	Engine performance	1	
Next Service:	156,000 Kms	Service History:	Yes	Noise	1	
Note: This report is	not a warranty		Coolant condition	1		
This report is a guide diagnostic testing ur	e only. Consideration is mad ndertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance	1	
full mechanical insp	ection prior to purchase an	d this can be arranged f	Radiator / Hoses (visual)	1		
Key				Transmission		
	= Rust $C = CT = Paint defect P = P$		3	Operation	V	
D-Dent 1	T = Taillt defect T = T	5C = 5t0	nie Criips	Noise	1	
		D S		Clutch	+	
				CV joints	1	
	$\mathcal{O}_{\mathcal{C}}$			Wheel bearings	V	
PT A				Brakes		
M				Performance	V	
			SC	Hand brake	1	
SC	10			Tyres (lowest observed tread		tyres)
6				Left front	deptiror	3.
			PT	Right front		3.
				Left rear	4.	
		P	PT P	Right rear		5.
Note: same defects	and blemishes may not be	displayed in the diagra		Spare	Yes	
	ion Comments	displayed in the diagra		Suspension		
	letaching on right side	e. Right side spot lig	ht lens is damaged	Suspension performance	V	
				Steering performance	V	
				Shock absorbers	1	
Conditions Du	ring Body Inspection		Air Conditioning / Heater			
Under Carriag	ge and Under Bonnet	Inspection Comm	Operation	V		
2WD			Electrical / Accessories			
				Head lights	1	
				Tail lights	1	
Interior Comn	nents			Indicators	1	
Seats:	Good			Dashboard warning lights	1	
Carpets:	Large rip on drivers side			Wipers (front & rear)	1	
Panels:	Good		Window winder FL	V		
Dashboard:	Good		Window winder FR	/		
General Comr	ments		Window winder RL	/		
				Window winder RR	/	
				Rear view mirrors	1	
				Radio (basic test only)	/	
Road Condition	ns During Test Drive	Dry	<del>.</del>	CD (basic test only)		
		I				

Road Conditions During Test Drive

Engine Timing Mechanism

Evidence of Cam Belt Replacement

Inspected by: Hoani Saunders

Published by: Mathew Green

Inspection Date: 23 Dec 2025

I have read and understood this condition guide:

NAME

SIGNATURE

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

1

1