

•	Report ID:	27,875,602	Version:	2
	Created:	19 Dec 2025		

Basic Condition Guide			Report ID:	27,875,602	ve	rsion: 2				
			Created:	19 Dec 2025						
Make:	Audi	Model:	A1	Requires						
Body Style:	Hatchback	Year:	2011	Engino		OK	Attention	N/A		
Rego No.:	PSF517	Rego Expiry:	26 Jun 2026	Engine			l	1		
WoF Expiry:	10 Mar 2026	Odometer:	128,911 Kms	Oil level		1				
Good No.:	27875602	VIN:	WAUZZZ8X0BB068502	Smoke & fu		/				
Next Service:	138,000 Kms	Service History:	No	Engine performance		1				
Note: This report is not a warranty					Noise Coolant condition					
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					Coolant condition  Cooling performance					
	ection prior to purchase an			- 31		/				
Key				Radiator / Hoses (visual)						
	= Rust $C = C$		3	Transmission						
D = Dent P	$\Gamma = Paint defect  P = P$	Pin dent SC = Sto	ne Chips	Operation		/				
		P	S	Noise		/				
				Clutch				/		
	$\sim$		PT	CV joints		/				
		1		Wheel bea	rings					
$\sim$ $\beta$	18			Brakes			I			
		Performan	ce	/						
					9					
					Tyres (lowest observed tread depth of tyres)  Left front 6.1 mm					
						6.1 mm				
						6.4 mr				
	$\leftarrow$	Left rear		6.4 m						
S		Right rear		6.5						
Note: some defects	and blemishes may not be	e displayed in the diagra	ım .	Spare		Yes				
Body Inspecti	on Comments			Suspension						
				Suspension	n performance	/				
				Steering pe	erformance	/				
				Shock abso	orbers	<b>/</b>				
Conditions Dur	Conditions During Body Inspection Dry					Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments					Operation 🗸					
2WD					Electrical / Accessories					
Oil weep Front left outer C.V boot needs to be re-secured, C.V grease seepage on C.V boot					5	~				
				Tail lights		•				
Interior Comm	nents			Indicators		/				
Seats:	Small hole on driv	vers seat lower cu	ushion	Dashboard	l warning lights	~				
							1			

Interior Comments					
Seats:	Small hole on drivers seat lower cushion				
Carpets:	Good				
Panels:	Scuffs on boot lid panel				
Dashboard:	Good				
General Comments					

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Miroslav Granich	
Inspection Date:	19 Dec 2025	

SIGNATURE		

1

1

1 1

1

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

I	ha	ve	rea	d	an	d	un	de	ers	to	OC	Į
t	his	co	nd	itio	on	g	uic	de:				