

# **Basic Condition Guide**

•	Report ID:	27,875,747	Version:	1
	Created:	19 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	1		
Engine performance	1		
Noise	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Coolant condition	~		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		<u> </u>	<u> </u>
Operation	V		
Noise	1		
Clutch			
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	J	<u> </u>	
Hand brake	.,		
	-1	t	
Tyres (lowest observed tread	depth of		. F
Left front			6.5 mm
Right front			6.6 mm
Left rear			4.7 mm
Right rear			5.7 mm
Spare	Yes		
Suspension		T	
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights	/		
Tail lights	<b>/</b>		
Indicators	/		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	<b>/</b>		
Window winder FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FR	V		
Window winder RL	/		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			·
Number of keys	1	<u> </u>	
Central locking	1		
Remote locking		· ·	<del>                                     </del>
Sat. nav. (basic test only)		+	
Reversing camera	1		<del>-</del>
neversing carriera		l	

Make:	Mitsubishi	Model:	Outlander
Body Style:	Wagon	Year:	2006
Rego No.:	HGL421	Rego Expiry:	28 Feb 2026
WoF Expiry:	12 Mar 2026	Odometer:	229,564 Kms
Good No.:	27875747	VIN:	7AT0CJ3MX14025918
Next Service:	232000kms	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Stone Chips in Windscreen Rear Bumper Reflector cracked

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Minor Engine Oil leak

Interior Comments	
Seats:	Poor
Carpets:	Average
Panels:	Poor
Dashboard:	Average

### **General Comments**

Rear Suspension noisy. Need to use manual key.

Static Noise from Front Right Speaker.

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Lindsay Malpas	
Published by:	Kieran Driver	
Inspection Date:	19 Dec 2025	

I have read and	understood
this condition a	uide.

NAME			