

•	Report ID: 27,876,297		Version:	2
	Created:	22 Dec 2025		

		ОК	Requires Attention	N/A
	Engine		Attention	14//
2026	Oil level	V		
9 Kms	Smoke & fumes	1		
F1RX19002592	Engine performance	1		
	Noise	1		
	Coolant condition	1		
been dismantled or The Vendor recommends a	Cooling performance	'		-
nal charge.	Radiator / Hoses (visual)	-		
	Transmission		<u> </u>	<u> </u>
W = Significant scuffs			<u> </u>	Ι
	Operation	- 1		-
S	Noise	/		
	Clutch			/
SP	CV joints	-		
The /	Wheel bearings			
SALV	Brakes		I	ı
	Performance	/		
	Hand brake	/		
	Tyres (lowest observed tread	depth of		
S	Left front			4.1 mn
3	Right front			4.0 mn
	Left rear		;	3.0 mm
<u>s</u>	Right rear			3.5 mm
	Spare	Yes		
	Suspension		_	
	Suspension performance	/		
	Steering performance	/		
	Shock absorbers	/		
	Air Conditioning / Heater			
	Operation		V	
	Electrical / Accessories			•
	Head lights	1		
	Tail lights	1		
	Indicators	~		
	Dashboard warning lights	1		
	Wipers (front & rear)	1		
	Window winder FL	1		
	Window winder FR	1		
	Window winder RL	1		
	Window winder RR	1		
	Rear view mirrors	1	1	
	Radio (basic test only)	-		_
			1	1
	CD (basic test only)	1		
	Number of keys			1
Kms	Central locking	/	-	-
	Remote locking	/		<u> </u>
	Sat. nav. (basic test only)			/
	Reversing camera	✓		1


Make:	Subaru	Model:	Exiga
Body Style:	Wagon	Year:	2008
Rego No.:	NAJ652	Rego Expiry:	10 Apr 2026
WoF Expiry:	11 Jul 2026	Odometer:	151,449 Kms
Good No.:	27876297	VIN:	7AT0GF1RX19002592
Next Service:	Unknown.	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have n diagnostic testing undertaken. The vehicle has been driven up to 50km/h from colo full mechanical inspection prior to purchase and this can be arranged for an addi

Key

* = DecalsS = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Oil leaks.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
Canada		

General Comments

Rear right door check strap faulty.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Flynn Burdon	
Published by:	Flynn Burdon	
Inspection Date:	22 Dec 2025	

I have read and understood
this condition guide:

NAME			