

## **Basic Condition Guide**

•	Report ID:	27,876,906	Version:	2
	Created:	22 Dec 2025		

U	ntuet	S Basi	c Condition Guide	Created: 22 Dec 2025			
Make:	BMW	Model:	1161			Requires	
Body Style:	Hatchback	Year:	2012		OK	Attention	N/A
Rego No.:	PBP782	Rego Expiry:	22 Feb 2026	Engine			
WoF Expiry:	20 Feb 2026	Odometer:	62,360 Kms	Oil level	/		
Good No.:	27876906	VIN:	WBA1A12070J207397	Smoke & fumes	<b>/</b>		
Next Service:	72,361kms	Service History:	No	Engine performance	<b>/</b>		
Note: This report is	,	Service History.	110	Noise	<b>/</b>		
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition	<b>/</b>		
	idertaken. The vehicle has b ection prior to purchase an		n from cold. The Vendor recommends a or an additional charge.	Cooling performance	<b>/</b>		
Key				Radiator / Hoses (visual)	/		
	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmission			
D = Dent P1	$\Gamma = Paint defect  P = Paint defect$	in dent SC = Sto	ne Chips	Operation	/		
	S			Noise	<b>/</b>		
				Clutch			<b>/</b>
	<u></u>		SC	CV joints			<b>/</b>
				Wheel bearings	<b>/</b>		
SC				Brakes			
				Performance	V		
				Hand brake	<b>'</b>		
	18			Tyres (lowest observed tread depth of tyres)			
				Left front		9	9.0 mm
			(Q)	Right front		9	9.0 mm
	$\angle$			Left rear		3	3.5 mm
	<u>s</u>	D		Right rear		4	I.0 mm
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare	N/A		
Body Inspection	on Comments			Suspension			
Tire repair kit in	stead of spare.			Suspension performance	/		
				Steering performance	1		
				Shock absorbers	1		
Conditions Dur	ing Body Inspection		Wet	Air Conditioning / Heater			
Under Carriag	e and Under Bonnet	Inspection Comm	ents	Operation	<b>/</b>		
				Electrical / Accessories			
				Head lights	V		
				Tail lights	1		
Interior Comments				Indicators	V		
Seats:	Seats: Good			Dashboard warning lights	1		
Carpets:	Good		Wipers (front & rear)	1			
Panels:	Good			Window winder FL	1		
Dashboard: Good				Window winder FR	1		
General Comm				Window winder RL	1		
				Window winder RR	1		
				Rear view mirrors	1		
				Radio (basic test only)	1		
		1			+	-	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	LukaAjitvan Woer	den
Published by:	Cody O'Neill	
Inspection Date:	19 Dec 2025	

I have read and understood this condition guide:

NAME			

SIGNATURE		

2

1

1

1

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only)

Reversing camera