

Basic Condition Guide

| • | Report ID: 27,877,669 | | Version: | 1 |
|---|-----------------------|-------------|----------|---|
| | Created: | 22 Dec 2025 | | |


| | ОК | Requires Attention | N/A |
|--------------------------------|----------|-----------------------|----------|
| Engine | | | _ |
| Oil level | V | | |
| Smoke & fumes | / | | |
| Engine performance | 1 | | |
| Noise | ~ | | |
| Coolant condition | 1 | | |
| Cooling performance | V | | |
| Radiator / Hoses (visual) | V | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | V |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 4 | 1.3 mm |
| Right front | | | 1.9 mm |
| Left rear | | 5 | 5.6 mm |
| Right rear | | 5 | 5.8 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | / | | |
| Dashboard warning lights | / | | |
| Wipers (front & rear) | / | | |
| Window winder FL | / | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | • | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | |
| Number of keys | 1 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | • | | |
| Reversing camera | / | | |

| KIA | Model: | Sportage |
|----------------|--|---|
| SUV | Year: | 2014 |
| HNL805 | Rego Expiry: | 17 Jul 2026 |
| 25 Mar 2026 | Odometer: | 144,579 Kms |
| 27877669 | VIN: | U5YPC81BSEL498823 |
| 151949 Kms | Service History: | No |
| not a warranty | | |
| | SUV HNL805 25 Mar 2026 27877669 | SUV Year: HNL805 Rego Expiry: 25 Mar 2026 Odometer: 27877669 VIN: 151949 Kms Service History: |

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Stone chip near CVA on windscreen.

| Conditions During Body Inspection | Dry | | | |
|---|-----|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | | |
| | | | | |

oil leaks

Skid plate held on with zip ties.

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |
| General Comments | | |

4WD.

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|-------------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Flynn Burdon | |
| Published by: | Nitiphum Yordsiri | |
| Inspection Date: | 22 Dec 2025 | |

| have read and understood |
|--------------------------|
| his condition quide |

| NAME | | | |
|------|--|--|--|