

•	Report ID: 27,878,310		Version:	1
	Created:	22 Dec 2025		

		Poci	c Condition Guide	Report ID:	27,878,310	Ve	rsion: 1	
	urner	S Dasi	C Condition Gaide	Created:	22 Dec 2025			
Make:	Suzuki	Model:	Ignis				Requires	
Body Style:	SUV	Year:	2018			OK	Attention	N/A
Rego No.:	LDP956	Rego Expiry:	07 May 2026	Engine				_
WoF Expiry:	05 Apr 2026	Odometer:	66,616 Kms	Oil level		/		ـــــــ
Good No.:	27878310	VIN:	JSAMFH11S00122655	Smoke & fu	ımes	/		<u> </u>
	Engine performance		/		ļ			
,				Noise	Noise 🗸			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Coolant condition		/		
				Cooling pe	rformance	/		
Key				Radiator / Hoses (visual)				
-	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	Transmission			
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation	Operation 🗸			
D		SD		Noise		/		
	$\overline{}$			Clutch	Clutch			
	<u></u>		SSC	CV joints		/		
	MA UT			Wheel bea	rings	/		
S				Brakes				
	IMP II			Performan	ce	V		
				Hand brake	e	'		
D	18			Tyres (lowest observed tread depth of tyres)				
				Left front		2.7 mm		
					:	4.0 mm		
SD S S S				Left rear		5.0 mm		
				Right rear		5.0 mm		
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes		
Body Inspecti	ion Comments			Suspensio	on			
				Suspension	n performance	V		Τ
				Steering pe	erformance	1		
				Shock abso	orbers	1		1
Conditions During Body Inspection Dry			Dry	Air Condit	ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation	-	V		$\overline{}$
Left front wheel arch missing body clip. Minor oil leak.				Electrical / Accessories				
				Head lights		V		Т
				Tail lights		1	1	+-
Interior Comments				Indicators		1		+-
Seats: Average				l warning lights	1		+-	
Carpets: Average		Wipers (fro		1		+-		
Panels: Average			Window w		1		+-	
. arreis.	7.1101490			TTITIO VV		-	-	+

	Interior Comm	nterior Comments			
	Seats:	Average			
	Carpets:	Average			
	Panels:	Average			
	Dashboard:	Average			
Conoral Comments		onts			

2WD.

Road Condition	s During Test Drive	Dry
Engine Timing N	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Flynn Burdon	
Published by:	Nitiphum Yordsiri	
Inspection Date:	22 Dec 2025	

I have read and understood		
this condition guide:	NAME	SIGNATURE

Window winder FR Window winder RL

Window winder RR

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Rear view mirrors

Number of keys

Central locking Remote locking 1

1

•

2

1

•