

## **Basic Condition Guide**

Report ID:	27,878,352	Version:	1
Created:	30 Dec 2025		

**Engine** 

OK

Requires Attention

N/A

Make:	Isuzu	Model:	D-MAX			
Body Style:	Utility	Year:	2016			
Rego No.:	JUL334	Rego Expiry:	06 May 2026			
WoF Expiry:	13 Nov 2026	Odometer:	285,676 Kms			
Good No.:	27878352	VIN:	MPATFS85JFT022506			
Next Service:	Next Service: 288,000		Yes			
Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						
Key						
S = Scratch R	= Rust $C = C$	rack *= Deca	ls $W = Significant scuffs$			

D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Ch	hips	
S		S D SC	S D SC		SDR
SSC					
	C C				S D SC
SDSC		S D SC	s sc		S D R SC W

Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Headlights faded

**Interior Comments** 

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Seats:	canvas covers fitted				
Carpets:	Average				
Panels:	Average	Average			
Dashboard:	Average				
General Comm	nents				
Air conditioning and heating systems ok. Handbrake travel excessive vehicle has had front impact damage both headlights broken mounts upper impact bar misshapen					
Road Condition	Road Conditions During Test Drive Dry				
Engine Timing Mechanism		Timing Chain			
Evidence of Cam Belt Replacement		Yes	No	Kms	
Inspected by:	Gary Adams				
Published by:	Anna Zandstra				
Inspection Date: 23 Dec 2025					

Oil level	<b>/</b>		
Smoke & fumes	<b>V</b>		
Engine performance	V		
Noise	<b>/</b>		
Coolant condition	\( \times \)		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission			
Operation	V		
Noise	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Clutch	V		
CV joints	V		
Wheel bearings	V		
Brakes			
Performance	V		
Hand brake		<b>V</b>	
Tyres (lowest observed trea	ad depth of ty	res)	•
Left front			7.0 mm
Right front			8.0 mm
Left rear			7.0 mm
Right rear			8.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	V		
Indicators	V		
Dashboard warning lights	V V		
Wipers (front & rear)	V		
Window winder FL	-		
Window winder FR	V		
Window winder RL		<b>/</b>	
Window winder RR	V		
Rear view mirrors	<b>/</b>		
Radio (basic test only)	<b>/</b>		
CD (basic test only)			<b>/</b>
Number of keys	1		
Central locking	V		
Remote locking	<b>'</b>		
Sat. nav. (basic test only)			/
Reversing camera			<b>/</b>

I have read a	nd understood
this condition	n guide:

N	Δ	M	F

SIGNATURE