

| Report ID: | 27,878,967  | Version: | 1 |
|------------|-------------|----------|---|
| Created:   | 22 Dec 2025 |          |   |


| Make: Mazda   |             | Model:           | Demio             |
|---------------|-------------|------------------|-------------------|
| Body Style:   | Hatchback   | Year:            | 2011              |
| Rego No.:     | JDN544      | Rego Expiry:     | 01 Sep 2026       |
| WoF Expiry:   | 02 Jun 2026 | Odometer:        | 87,037 Kms        |
| Good No.:     | 27878967    | VIN:             | 7AT0C12HX15356310 |
| Next Service: | 95534km     | Service History: | No                |

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

### **Body Inspection Comments**

Missing Parcel Tray.

Missing Wheel Trim Front Left.

Wheel Trims Front Right and Rear Left are cracked.

| Conditions During Body Inspection                   | Dry |  |  |
|---|-----|--|--|
| Under Carriage and Under Ronnet Inspection Comments |     |  |  |

Engine and Transmission oil seepage.

| Interior Comments |                  |  |  |
|-------------------|------------------|--|--|
| Seats:            | Good             |  |  |
| Carpets:          | Good             |  |  |
| Panels:           | Good             |  |  |
| Dashboard:        | Good             |  |  |
| General Comm      | General Comments |  |  |

# Front Wheel Drive.

| Road Conditions During Test Drive |             | Dry          |
|-----------------------------------|-------------|--------------|
| Engine Timing Mechanism           |             | Timing Chain |
| Evidence of Cam Belt Replacement  |             | Yes No Kms   |
| Inspected by:                     | Haden Brown |              |
| Published by:                     | Haden Brown |              |
| Inspection Date:                  | 22 Dec 2025 |              |

| I have read and understood |
|----------------------------|
| this condition guide:      |

| NAME |  |  |  |
|------|--|--|--|

|                                | ОК       | Requires<br>Attention | N/A  |
|--------------------------------|----------|-----------------------|------|
| Engine                         |          |                       |      |
| Oil level                      | <b>/</b> |                       |      |
| Smoke & fumes                  | <b>/</b> |                       |      |
| Engine performance             | <b>/</b> |                       |      |
| Noise                          | V        |                       |      |
| Coolant condition              |          |                       |      |
| Cooling performance            | 1        |                       |      |
| Radiator / Hoses (visual)      | ~        |                       |      |
| Transmission                   |          |                       |      |
| Operation                      | ~        |                       |      |
| Noise                          | ~        |                       |      |
| Clutch                         |          |                       |      |
| CV joints                      | ~        |                       |      |
| Wheel bearings                 | ~        |                       |      |
| Brakes                         |          |                       |      |
| Performance                    | ~        |                       |      |
| Hand brake                     | ~        |                       |      |
| Tyres (lowest observed tread d | epth of  | tyres)                |      |
| Left front                     |          |                       | 3 mm |
| Right front                    |          |                       | 4 mm |
| Left rear                      |          |                       | 4 mm |
| Right rear                     |          |                       | 4 mm |
| Spare                          | Yes      |                       |      |
| Suspension                     |          |                       |      |
| Suspension performance         | ~        |                       |      |
| Steering performance           | ~        |                       |      |
| Shock absorbers                | ~        |                       |      |
| Air Conditioning / Heater      |          |                       |      |
| Operation                      | ~        |                       |      |
| Electrical / Accessories       |          |                       |      |
| Head lights                    | ~        |                       |      |
| Tail lights                    | 1        |                       |      |
| Indicators                     | /        |                       |      |
| Dashboard warning lights       | V        |                       |      |
| Wipers (front & rear)          | ~        |                       |      |
| Window winder FL               | •        |                       |      |
| Window winder FR               | ~        |                       |      |
| Window winder RL               | 1        |                       |      |
| Window winder RR               | ~        |                       |      |
| Rear view mirrors              | ~        |                       |      |
| Radio (basic test only)        | ~        |                       |      |
| CD (basic test only)           | 1        |                       |      |
| Number of keys                 | 1        |                       |      |
| Central locking                | 1        |                       |      |
| Remote locking                 | 1        |                       |      |
| Sat. nav. (basic test only)    |          |                       | ~    |
| Reversing camera               |          |                       |      |
|                                |          |                       |      |

| SIGNATURE |  |  |  |
|-----------|--|--|--|