

| Report ID: 27,879,304 | | Version: | 1 |
|-----------------------|-------------|----------|---|
| Created: | 23 Dec 2025 | | |

| | ОК | Requires Attention | N/A |
|------------------------------|----------|-----------------------|------|
| Engine | | | |
| Oil level | ' | | |
| Smoke & fumes | V | | |
| Engine performance | 1 | | |
| Noise | V | | |
| Coolant condition | V | | |
| Cooling performance | V | | |
| Radiator / Hoses (visual) | V | | |
| Transmission | | | • |
| Operation | V | | |
| Noise | V | | |
| Clutch | | | 1 |
| CV joints | V | | |
| Wheel bearings | / | | |
| Brakes | , | | |
| Performance | V | | |
| Hand brake | 1 | | |
| Tyres (lowest observed tread | depth of | tyres) | |
| Left front | | | 3 mr |
| Right front | | | 3 mr |
| Left rear | | | 5 mi |
| Right rear | | | 5 mr |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | V | | |
| Tail lights | 1 | | |
| Indicators | ~ | | |
| Dashboard warning lights | 1 | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | ~ | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | 1 | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | 1 | | |
| Number of keys | 2 | • | |
| Central locking | / | | |
| Remote locking | ~ | | |
| Sat. nav. (basic test only) | | | ~ |
| Reversing camera | | V | |

| | nue | | | |
|-------------------------|---|-------------------------|--|--|
| Make: | Toyota | Model: | Prius | |
| Body Style: Hatchback | | Year: | 2008 | |
| Rego No.: | ENZ231 | Rego Expiry: | 02 Jan 2026 | |
| WoF Expiry: 19 Oct 2026 | | Odometer: | 323,600 Kms | |
| Good No.: 27879304 | | VIN: | JTDKB22UX07755484 | |
| Next Service: | 310388km | Service History: | No | |
| diagnostic testing ur | only. Consideration is made | een driven up to 50km/h | orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge. | |
| Кеу | | | | |
| S = Scratch R | = Rust $C = C$ | rack *= Deca | ls W = Significant scuffs | |
| D = Dent P | $\Gamma = Paint defect P = Paint defect$ | in dent SC = Stor | ne Chips | |
| PW | | W PW | PW | |
| | | | | |
| | | | SDW | |
| DPTC | | | | |
| - | 18 | | 1 | |
| | | 11 — | | |
| | | | | |
| SC W | | | | |
| | | | W | |
| | | | | |
| S | S | S SDP | SSD | |
| | | 3 351 | 3 35 | |
| | and blemishes may not be | displayed in the diagra | m | |
| | on Comments | | | |
| Tailgate handle | broken. r needs servicing. | | | |
| Troncingin impo | . Hoode oor violing. | | | |
| | | | T | |
| | ing Body Inspection | | Dry | |
| Under Carriag | e and Under Bonnet | Inspection Comm | ents | |
| | | | | |
| | | | | |
| | | | | |
| Interior Comn | nents | | | |
| Seats: | Average | | | |
| Carpets: | drivers floor is wo | rn | | |
| Panels: | Average | | | |

| Road Condition | s During Test Drive | Dry | | |
|----------------------------------|---------------------|------------|-----|----|
| Engine Timing I | Mechanism | Timing Cha | ain | |
| Evidence of Cam Belt Replacement | | Yes | No | Km |
| Inspected by: | Haden Brown | | | |
| Published by: | Haden Brown | | | |
| Inspection Date: | 23 Dec 2025 | | | |
| | | | | |

I have read and understood this condition guide:

Dashboard:

General Comments Front Wheel Drive.

Average

NAME _

SIGNATURE