

Report ID:	27,879,857	Version:	1
Created:	23 Dec 2025		

		Raci	c Condition Guide	Report ID:	27,879,857	Ve	ersion: 1	
	urner			Created:	23 Dec 2025			
Make:	Hyundai	Model:	Tucson				Requires	
Body Style:	suv	Year:	2016	Engine		OK	Attention	N/A
Rego No.:	JZJ644	Rego Expiry:	06 Feb 2026	_ Engine				1
WoF Expiry:	24 Jun 2026	Odometer:	139,012 Kms	Oil level		7	 	
Good No.:	27879857	VIN:	KMHJ3814MHU204210	Smoke & fu		+ -	-	1
Next Service:	139,000 Kms	Service History:	Yes	Engine per	Tormance	7	 	
lote: This report i	is not a warranty			Noise		+ -	1	
his report is a guid	le only. Consideration is mad	e for age and mileage. P	arts have not been dismantled or	Coolant co		1	<u> </u>	<u> </u>
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling pe		/	<u> </u>	
Кеу					Hoses (visual)	/		
	R = Rust $C = C$			Transmission				Т
D = Dent F	PT = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		V	<u> </u>	-
	W			Noise		-	 	
				Clutch			 	\ <u>'</u>
	(O)=		S D SC	CV joints		/	 	
S SC /				Wheel bea	rings	/	<u> </u>	
-	118			Brakes				
			SC	Performan		/	<u> </u>	
				Hand brake		/		
sc				Tyres (lowest observed tread depth of tyres)				
				Left front		6.4 mm		
				Right front				6.4 mm
S W W			Left rear		4.1 mr		4.1 mm	
			Right rear		4.3 m		4.3 mm	
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes				
, ,	tion Comments			Suspensio	n			
Holes in rear bumper lower plastic trim			Suspension	n performance	/	<u> </u>	<u> </u>	
				Steering pe	erformance	/		
				Shock abso	orbers	/		
Conditions During Body Inspection Wet				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments			Operation		/			
2WD				Electrical / Accessories				
				Head light:	5	/		
				Tail lights		/		
Interior Comments			Indicators		/			
Seats:	Slight wear on dri	drivers seat		Dashboard	l warning lights	/		
Carpets:	Good			Wipers (fro	nt & rear)	/		
Panels:	Good	Good		Window w	inder FL	~		
Dashboard:	Good	ood			inder FR	1		
General Comments				Window w	inder RL	1		
Noise coming	from front right tyre			Window w	inder RR	1	1	
				Rear view r	mirrors	1	1	
							+	+

Road Conditions During Test Drive		Wet			
Engine Timing Mechanism			Timing Chain		
	Evidence of Cam Belt Replacement		Yes	No	Kms
	Inspected by:	Hoani Saunders			
	Published by:	Robert Chardon			
	Inspection Date:	23 Dec 2025			
				-	

have read and understood
this condition quide

NAME			

GNATURE	

Radio (basic test only) CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

2

1

•