

Report ID:	27,881,598	Version:	1
Created:	06 Jan 2026		


Make:	Volkswagen	Model:	T5
Body Style:	Van	Year:	2014
Rego No.:	HPZ122	Rego Expiry:	25 Aug 2026
WoF Expiry:	25 Feb 2026	Odometer:	261,224 Kms
Good No.:	27881598	VIN:	WV1ZZZ7HZEH121212
Next Service:	273,000kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Number plate light not working, L rear screen plastic cover missing, passenger seat torn, first and second row seat torn, 3rd row seat belt torn and worn, missing spare tyre,

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Poor
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

One remote key not working, central lock not working, 1 and 2 blower ac fan not working, steering wheel worn, window cracked cva, dash board light on, missing one blade key.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Kms
Inspected by:	Marlon Espena
Published by:	Marlon Espena
Inspection Date:	06 Jan 2026

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4 mm
Right front			4 mm
Left rear			7 mm
Right rear			7 mm
Spare		No	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	3		
Central locking		✓	
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____