

Basic Condition Guide

Report ID:	27,883,680	Version:	1
Created:	28 Dec 2025		

	Jeep	Model:	Grand Cherokee
Body Style:	Wagon	Year:	2012
Rego No.:	NHL627	Rego Expiry:	16 Aug 2026
WoF Expiry:	16 Jan 2026	Odometer:	152,151 Kms
Good No.:	27883680	VIN:	1C4RJFHJ4DC570401
Next Service:	122000km	Service History:	No
iagnostic testing ur	only. Consideration is mad	oeen driven up to 50km	Parts have not been dismantled or /h from cold. The Vendor recommends a for an additional charge.
ey Caratah D	Dust C (Swark * Dos	als W Cignificant south
	= Rust $C = CT = Paint defect P = F$	Crack * = Dec Pin dent SC = Sto	als W = Significant scuff one Chips
		\square	
			SW
	MA WIF		
SC W			
	IMT II		
W			
	-		
		P W	
	and blemishes may not be	e displayed in the diag	ram
Body Inspecti	on Comments		
C. IIII	in Della Landia		Desi
	ring Body Inspection	h la constitue Come	Dry
	ring Body Inspection ge and Under Bonne	t Inspection Comi	•
		t Inspection Comi	•
		t Inspection Comi	•
	ge and Under Bonne	t Inspection Comi	•
Under Carriag	ge and Under Bonner	t Inspection Comi	•
Under Carriag Interior Comm Seats:	nents Average	t Inspection Comi	•
Interior Comm Seats: Carpets:	nents Average Average	t Inspection Comi	•
Under Carriag	nents Average Average Average	t Inspection Comi	•
Interior Comm Seats: Carpets: Panels: Dashboard:	nents Average Average Average Average Average Average	t Inspection Comi	•
Interior Comm Seats: Carpets: Panels:	nents Average Average Average Average Average Average	t Inspection Com	•
Interior Common Seats: Carpets: Panels: Dashboard: General Common	nents Average Average Average Average Average Exercises Services S	t Inspection Comi	•
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	nents Average Average Average Average Average Exercises Services S	t Inspection Comi	•

		Requires	
	OK	Attention	N/A
Engine			<u> </u>
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	•		
Coolant condition	•		
Cooling performance	~		
Radiator / Hoses (visual)	'		
Transmission			
Operation	~		
Noise	1		
Clutch			
CV joints	/		
Wheel bearings	'		
Brakes			
Performance	1		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4 mm
Right front			4 mm
Left rear			2 mm
Right rear			4 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater	l .		
Operation	1		
Electrical / Accessories		<u> </u>	
Head lights	/		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	/		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	2	l	L
Central locking	- -	1	
	1		
Remote locking Sat. nav. (basic test only)	_		· /
	J		
Reversing camera			

I have read and understood
this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 28 Dec 2025

Haden Brown

Haden Brown

N	Δ	M	F

Timing Chain

No

Yes

SIGNATURE

Kms