


Make:	Hyundai	Model:	Iload
Body Style:	Van	Year:	2019
Rego No.:	MHZ897	Rego Expiry:	25 Feb 2026
WoF Expiry:	12 Sep 2026	Odometer:	268,137 Kms
Good No.:	27883857	VIN:	KMFWBX7KMLU100394
Next Service:	268000	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Stone chips /cracked on front windscreen  
Windscreen moulding missing  
Spare wheel tyre damaged( bolt )

Conditions During Body Inspection

Wet

## Under Carriage and Under Bonnet Inspection Comments

Rear wheel drive  
Engine oil leaks

## Interior Comments

Seats: Average  
Carpets: Average  
Panels: Average  
Dashboard: Good

## General Comments

Service due

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Xinghui Lin
Published by:	Xinghui Lin
Inspection Date:	12 Jan 2026

Report ID:	27,883,857	Version:	1
Created:	12 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			6.5 mm
Right front			6.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_