

•	Report ID:	27,884,061	Version:	1
	Created:	29 Dec 2025		

OK

Requires Attention

N/A

	1000	Raci	c Condition Guide	Report IL
	nuer	<u> </u>		Created:
Make:	Mitsubishi	Model:	Outlander	
Body Style:	Wagon	Year:	2007	
	LUP797		28 Feb 2026	Engine
Rego No.:		Rego Expiry:		Oil level
WoF Expiry:	27 Nov 2026	Odometer:	199,704 Kms	Smoke &
Good No.:	27884061	VIN:	7AT0CJ3MX18200319	Engine p
Next Service:	201,650 Kms	Service History:	No	Noise
Note: This report is a guide	•	e for age and mileage. Pa	arts have not been dismantled or	Coolant o
diagnostic testing und		een driven up to 50km/l	n from cold. The Vendor recommends a	Cooling p
Key				Radiator
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmis
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operatio
	W	PT SD	SP	Noise
	vv s	J	34	Clutch
			S	CV joints
				Wheel be
PT SC W				Brakes
	Mr II			Performa
				Hand bra
D SC	8			Tyres (lov
				Left front
			(Q)	Right froi
	$\angle$ $\overline{}$ $\overline{}$			Left rear
P	W	S P P	P	Right rea
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare
Body Inspection	on Comments			Suspens
Front right park	light isn't working			Suspensi
Right rear bumper reflector cracked				Steering
				Shock ab
Conditions Duri	ing Body Inspection		Dry	Air Cond
Under Carriage and Under Bonnet Inspection Comments				Operation

Engine				
Oil level	V			
Smoke & fumes	V			
Engine performance	<b>V</b>			
Noise	1			
Coolant condition	~			
Cooling performance	1			
Radiator / Hoses (visual)	1			
Transmission				
Operation	<b>/</b>			
Noise	<b>/</b>			
Clutch			<b>'</b>	
CV joints	V			
Wheel bearings	~			
Brakes				
Performance	V			
Hand brake	~			
Tyres (lowest observed tread	depth of t	yres)		
Left front		2	2.6 mm	
Right front		3	3.4 mm	
Left rear		5	5.9 mm	
Right rear		6.0 mm		
Spare	Yes	Yes		
Suspension				
Suspension performance	V			
Steering performance	V			
Shock absorbers	1			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights		<b>/</b>		
Tail lights	~			
Indicators	<b>/</b>			
Dashboard warning lights	<b>V</b>			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	ow winder FR			
Window winder RL	~			
Window winder RR		<b>✓</b>		
Rear view mirrors	V			
Radio (basic test only)	V			
CD (basic test only)	<b>/</b>			
Number of keys	1			
Central locking	1			

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		
4WD		

Oil seep

Surface rust on top radiator support panel and has had rust repairs on underside of vehicle

Interior Comments			
Seats:	Slight wear on drivers seat		
Carpets:	Good		
Panels:	Average		
Dashboard:	Good		
General Comments			

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Malcolm Thomas	
Inspection Date:	29 Dec 2025	

I have read and understood	k
this condition quide	

NAME		

IGNATURE		

1

Remote locking

Sat. nav. (basic test only) Reversing camera