

Report ID:	27,886,587	Version:	1
Created:	29 Dec 2025		

Requires Attention	N/A				
Transmission					
	~				
of tyres)					
	2.9 mr				
	3.5 mr				
	3.0 mr				
	2.0 mr				
 S					
	Τ				
	Ι				
· /					
· /					
	1				
	1				
	1				
	1				
1	\vdash				
	1				
1	1				
1	-				
	"				

UT	nuel	S Basi	c Condition Guide		
Make:	Honda	Model:	FIT		
Body Style:	Hatchback	Year:	2004		
Rego No.:	JMY513	Rego Expiry:	26 Jan 2026		
WoF Expiry:	07 Mar 2026	Odometer:	184,324 Kms		
Good No.:	27886587	VIN:	7AT08G2YX15146245		
Next Service:	177,000 Kms	Service History:	No		
diagnostic testing un	only. Consideration is made	een driven up to 50km/h	orts have not been dismantled or I from cold. The Vendor recommends a or an additional charge.		
	= Rust C = C T = Paint defect P = Pi W				
SC W			S SC W		
PT		PT P	WP		
Body Inspection	and blemishes may not be on Comments	displayed in the diagra	m		
Surface rust in I		aillights aren't work	ing		
Conditions Dur	ing Body Inspection		Dry		
2WD Oil seep	e and Under Bonnet underside of vehicle	Inspection Comm	ents		
Interior Comm	nents				
Seats:	Average				
Carpets:	Average				
Panels:	Good				
Dashboard:	Good				
General Comn	nents				
A/C works but is	sn't blowing through c	entre air vents			

have read and understood
this condition quide

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 29 Dec 2025

Hoani Saunders

Brad Lucas

Engine Timing Mechanism

Inspected by:

Published by:

Dry

Timing Chain

Yes

NAME			

No