

Report ID:	27,886,766	Version:	2
Created:	31 Dec 2025		


Requires

Make:	Mazda	Model:	Mazda3
Body Style:	Sedan	Year:	2006
Rego No.:	DGK109	Rego Expiry:	06 Aug 2026
WoF Expiry:	16 Jan 2026	Odometer:	284,638 Kms
Good No.:	27886766	VIN:	JM0BK10F100188081
Next Service:	284400	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left wing mirror cover missing

Left tail light damaged

Minor stone chips on windscreen

Right tyre wall damaged

right tyre wan damaged	
Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Left outer CV boot torn

Front left shock or suspension needs attention

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Left rear window switch on drivers switch does not operate properly

Radio/AC screen does not operate

Due for a service

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jaykib Collins	
Published by:	Jaykib Collins	
Inspection Date:	28 Dec 2025	

I have read and understood
this condition guide:

NAME			

SIGNATURE

	OK	Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	/		
Engine performance	V V		
Noise			
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints		'	
Wheel bearings	/		
Brakes			
Performance	~		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			2.0 mm
Right front		3	3.0 mm
Left rear		(6.0 mm
Right rear			1.0 mm
Spare	Yes		
Suspension			
Suspension performance		'	
Steering performance	/		
Shock absorbers		'	
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	/		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL		~	
Window winder RR	~		
Rear view mirrors	V		
Radio (basic test only)	~		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking		'	
Sat. nav. (basic test only)			
Sat. nav. (basic test only) Reversing camera			V