

Basic Condition Guide


•	Report ID:	27,886,905	Version:	1
	Created:	29 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	V		
Noise	/		
Clutch	V V		
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	_		
Tyres (lowest observed tread d	epth of	tvres)	
Left front			4.5 mm
Right front		-	5.0 mm
Left rear			2.0 mm
Right rear			2.5 mm
Spare	Yes		
Suspension	100		
Suspension performance	1		
Steering performance	1		
Shock absorbers	<i>y</i>		
Air Conditioning / Heater			
		l	Τ
Operation Electrical / Accessories			
	/		
Head lights			-
Tail lights	<i>'</i>		
Indicators Deals and married limbs			
Dashboard warning lights	V		-
Windowwindor Fl	<i>'</i>		-
Window winder FL			-
Window winder FR	V		-
Window winder RL	1		-
Window winder RR	•		-
Rear view mirrors	/		
Radio (basic test only)	/		-
CD (basic test only)	2		<u> </u>
Number of keys	2	1	
Central locking	/		<u> </u>
Remote locking	•		
Sat. nav. (basic test only)			/
Reversing camera			

Make:	Volkswagen	Model:	Golf
Body Style:	Wagon	Year:	2008
Rego No.:	KEM649	Rego Expiry:	06 Feb 2026
WoF Expiry:	22 Dec 2026	Odometer:	204,219 Kms
Good No.:	27886905	VIN:	WVWZZZ1KZ8M356433
Next Service:	213000	Service History:	No

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

itey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left Sill Dent, Door Trim Sagging.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Oil Leak lower engine area.

Interior Comments			
Seats:	Poor		
Carpets:	Poor		
Panels:	Poor		
Dashboard:	Poor		
General Comments			

Rear Tyres Inside Edge Worn.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	✓ No	Kms
Inspected by:	Liam Walls			
Published by:	Liam Walls			
Inspection Date:	29 Dec 2025			

I have read and understood	k
this condition quide	

NAME			