

•	Report ID:	27,886,914	Version:	2
	Created:	29 Dec 2025		

Лake:	Mazda	Model:	Premacy
ody Style:	Wagon	Year:	2005
Rego No.:	HKT298	Rego Expiry:	14 Feb 2026
NoF Expiry:		Odometer:	168,499 Kms
Good No.:	27886914	VIN:	7AT0C133X14107231
Next Service:		Service History:	No
agnostic testing ur II mechanical insp	e only. Consideration is mandertaken. The vehicle has		arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge.
ey Caratala D	D	C	la
		: Crack * = Deca : Pin dent SC = Sto	
			ne criips
s sc	W [S SC W S SC	W SC
	$(0)_{\ell}$		SC W
SC W			
M	19 11		
		1 +	S R SC
S R SC	10		
<u> </u>			
			S
s sc	W	R SC W S P SC	W S SC
	and blemishes may not	be displayed in the diagra	am
ote: some defects	and blemishes may not lon Comments	be displayed in the diagra	am
ote: some defects	ion Comments	be displayed in the diagra	am
ote: some defects Body Inspecti Front bumper n	ion Comments	be displayed in the diagra	am
ote: some defects Body Inspecti Front bumper n	ion Comments nisaligned	be displayed in the diagra	am
ote: some defects Body Inspecti Front bumper n Right wing mirr	on Comments nisaligned or housing cracked		Dry
ote: some defects Body Inspecti Front bumper n Right wing mirr Conditions Du	on Comments nisaligned or housing cracked ring Body Inspection		Dry
ote: some defects Body Inspecti Front bumper n Right wing mirr Conditions Du	on Comments nisaligned or housing cracked ring Body Inspection ge and Under Bonne	1	Dry
ote: some defects Body Inspecti Front bumper n Right wing mirr Conditions Du Under Carriag	on Comments nisaligned or housing cracked ring Body Inspection ge and Under Bonne	1	Dry
ote: some defects Body Inspecti Front bumper n Right wing mirr Conditions Du Under Carriag Juderbody surf	on Comments nisaligned or housing cracked ring Body Inspection ge and Under Bonne	1	Dry
ote: some defects Body Inspecti Front bumper n Right wing mirr Conditions Du Under Carriag Juderbody surf	inisaligned or housing cracked ring Body Inspection ge and Under Bonne face rust	1	Dry
ote: some defects Body Inspecti Front bumper in Right wing mirr Conditions Du Under Carriag Underbody surf Engine oil leak	ion Comments inisaligned or housing cracked ring Body Inspection ge and Under Bonne face rust	1	Dry
conditions Du Under Carriag Underbody surf Engine oil leak Interior Comm Seats:	inisaligned or housing cracked ring Body Inspection ge and Under Bonne face rust Average	1	Dry
cote: some defects Body Inspecti Front bumper in Right wing mirr Conditions Du Under Carriag Inderbody surf Ingine oil leak	ion Comments inisaligned or housing cracked ring Body Inspection ge and Under Bonne face rust	1	Dry

	ОК	Requires Attention	N/A
Engine		711111111111111111111111111111111111111	,
Oil level	/		
Smoke & fumes	/		
Engine performance	1		
Noise	/		
Coolant condition	1		
Cooling performance	\(\times \) \(\t		
Radiator / Hoses (visual)	/		
Transmission			
Operation	1		
Noise	1		
Clutch			
CV joints	1		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tvres)	
Left front		-):;	4 mm
Right front			4 mm
Left rear			5 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	<i>\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}</i>		
Air Conditioning / Heater		l	
Operation	/	Ι	
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	1		
Dashboard warning lights	✓		
Wipers (front & rear)	V		
Window winder FL			
Window winder FR	· ·		
Window winder RL			
Window winder RR	/	 	
Rear view mirrors	_		
Radio (basic test only)	/		
CD (basic test only)		-	
Number of keys	2	<u> </u>	Ь
Central locking	·	1	
Remote locking	<i>J</i>		
Sat. nav. (basic test only)			
Reversing camera			
neversing current		<u> </u>	

Road Condition	s During Test Drive	Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sione Mae	
Published by: Sione Mae		
Inspection Date:	29 Dec 2025	

I have read and understood this condition guide:

General Comments One remote key not working

NAME _

SIGNATURE