

Basic Condition Guide

•	Report ID:	27,887,385	Version:	1
	Created:	31 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	'		
Smoke & fumes	~		
Engine performance	1		
Noise	•		
Coolant condition	V		
Cooling performance	1		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	1		
Clutch			~
CV joints			V
Wheel bearings	•		
Brakes			
Performance	'		
Hand brake	~		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front		(6.9 mm
Right front		6	6.7 mm
Left rear		3	3.5 mm
Right rear		3	3.5 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	'		
Tail lights	/		
Indicators	1		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	1		
Window winder FL	'		
Window winder FR	1		
Window winder RL			/
Window winder RR			V
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			'
Number of keys	1		
Central locking	•		
Remote locking	'		
Sat. nav. (basic test only)			
Reversing camera	/		

Make:	LDV	Model:	G10
Body Style:	Van	Year:	2019
Rego No.:	LZZ325	Rego Expiry:	18 Feb 2026
WoF Expiry:	30 Jan 2026	Odometer:	166,394 Kms
Good No.:	27887385	VIN:	LSKG4GL10JA086190
Next Service:	171,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			
OMP			

Interior Comments Wear on drivers seat Seats: Good Carpets: Panels: Average Dashboard: Good **General Comments**

Road Conditions During Test Drive Dry Timing Chain **Engine Timing Mechanism** Evidence of Cam Belt Replacement Yes No Kms Hoani Saunders Inspected by: Published by: Mathew Green Inspection Date: 31 Dec 2025

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			