

| • | Report ID: 27,887,545 | | Version: | 1 |
|---|-----------------------|-------------|----------|---|
| | Created: | 03 Jan 2026 | | |

ОК

Requires Attention


N/A

| Make: | Toyota | Model: | Aurion |
|--|-------------|--------------|-------------------|
| Body Style: | Sedan | Year: | 2011 |
| Rego No.: | NDR241 | Rego Expiry: | 28 Feb 2026 |
| WoF Expiry: | 30 Oct 2026 | Odometer: | 316,564 Kms |
| Good No.: | 27887545 | VIN: | 6T153KK400X353491 |
| Next Service: 302000 Service History: No | | | |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

| Conditions During Body Inspection | Wet | |
|---|-----|--|
| Under Carriage and Under Bonnet Inspection Comments | | |

Right outer cv boot split, grease on calliper

Oil leaks front cover area

Overdue service

Front tyres worn on edges

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats: | Good | | |
| Carpets: | Good | | |
| Panels: | Good | | |
| Dashboard: | Good | | |
| General Comments | | | |

| Road Conditions During Test Drive | | Wet | | |
|-----------------------------------|--------------|--------------|----|-----|
| Engine Timing Mechanism | | Timing Chain | | |
| Evidence of Cam Belt Replacement | | Yes | No | Kms |
| Inspected by: | Greg Morgan | | | |
| Published by: | Sean Butcher | | | |
| Inspection Date: | 29 Dec 2025 | | | |

| I have read | and | lunc | lerstood | |
|-------------|-------|-------|----------|--|
| this condit | ion g | guide | 2: | |

| NAME | | | |
|------|--|--|--|

| Engine | | | |
|--------------------------------|------------|----------|----------|
| Oil level | / | | |
| Smoke & fumes | ✓ | | |
| Engine performance | \(\tau \) | | |
| Noise | ✓ | | |
| Coolant condition | > | | |
| Cooling performance | V | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | / | | |
| Clutch | | | |
| CV joints | | / | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | | / | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | , | 1.0 mm |
| Right front | | 2 | 2.0 mm |
| Left rear | | Ę | 5.0 mm |
| Right rear | | 3 | 3.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | / | | |
| Dashboard warning lights | / | | |
| Wipers (front & rear) | / | | |
| Window winder FL | / | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | ' |
| Reversing camera | | | |
| | | | |

| SIGNATURE | | |
|-----------|--|--|