

## Basic Condition Guida

Report ID: 27,887,566		Version:	1
Created:	29 Dec 2025		

	umer	S Dasi	C Condition Guide	Created:	29 Dec 2025				
Make:	Nissan	Model:	Tiida			01/	Requires		
Body Style:	Hatchback	Year:	2005	Engino		OK	Attention	N/A	
Rego No.: JTE915		Rego Expiry:	15 Jun 2026	Engine Oil level		V			
WoF Expiry:	09 Oct 2026	Odometer:	142,698 Kms	Smoke & fumes		1			
Good No.:	27887566	VIN:	7AT0DH78X15086782			1	<u> </u>	<u> </u>	
Next Service:	no sticker	Service History:	No	Engine performance Noise		·			
Note: This report is	not a warranty	Coolant condition							
This report is a guide diagnostic testing ur	only. Consideration is madadertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	arts have not been dismantled or a from cold. The Vendor recommends a	Cooling pe		1	<u> </u>	<u> </u>	
full mechanical insp	ection prior to purchase an		Hoses (visual)	1					
Key				Transmiss					
S = Scratch $R = Rust$ $C = Crack$ *= Decals $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$					Operation				
D=Dent PT=Paint derect P=Pin dent SC=Stone Cnips						_	•	<u> </u>	
S PT SC W D PT P W P W PT W								-	
				Clutch CV joints		1		<u> </u>	
	$\mathcal{O}_{\mathcal{C}}$		D PT W		rings	1		<u> </u>	
SC W		·   -		Wheel bearings  Brakes					
M	Mar II		A FILL	Performan	ce	V			
		$\parallel \parallel \parallel \perp$		Hand brake		1		<u> </u>	
S SC	10			Tyres (lowest observed tread depth of tyres)					
330 1010					Left front 1 mm				
			Right front			2 mm			
		Left rear				5 mm			
DW	CW D	Right rear				5 mm			
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare Yes					
	on Comments	. displayed in the diagra		Suspension	n				
Front bumper m				•	n performance	V			
					erformance	1			
				Shock abso		1			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater					
Under Carriag	je and Under Bonnet	Inspection Comm	ents	Operation 🗸					
Underbody surf				Electrical /	'Accessories				
Engine oil seep	age			Head light:	5	V			
				Tail lights		1			
Interior Comments				Indicators		1			
Seats:	Poor		Dashboard	l warning lights	1				
Carpets:	Average			Wipers (front & rear)		1			
Panels: Average				Window w	inder FL	1			
Dashboard: Average				Window w	inder FR	1			
General Comments					inder RL	1			
Foggy reverse light					inder RR	1			
Suspected shudder from transmission under load, requires further investigation					mirrors	1			
				Radio (basi	c test only)	1			

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 29 Dec 2025

Sione Mae

Sione Mae

Engine Timing Mechanism

Inspected by:

Published by:

Dry

Timing Chain

Yes

NAME			

No

SIGNATURE		

2

1

1

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms