

## **Basic Condition Guide**

Report ID:	27,887,578	Version:	1	
Created:	30 Dec 2025			

	umei			Created:	30 Dec 2025				
Make:	Mazda	Model:	Axela				Requires		
Body Style:	Sedan	Year:	2005		0	K	Attention	N/A	
Rego No.:	HFU715	Rego Expiry:	13 Apr 2026	Engine		. [			
WoF Expiry:	11 Oct 2026	Odometer:	308,537 Kms	Oil level					
Good No.: 27887578		VIN:	7AT0C13JX12210750	Smoke & fu					
Next Service: 23/10/25 Service History: No				Engine performance					
Note: This report is		Service History.	THE STATE OF THE S	Noise					
This report is a guide	only. Consideration is mad	le for age and mileage.	Coolant co		_	· ·			
diagnostic testing un full mechanical inspe	ndertaken. The vehicle has be ection prior to purchase ar	been driven up to 50kn nd this can be arranged	Cooling pe	erformance	/				
Key				Radiator / Hoses (visual)					
S = Scratch R	= Rust C = C	Crack *= Dec	cals W = Significant scuffs	Transmiss	ion				
D = Dent P1	$\Gamma = Paint defect  P = F$	Pin dent $SC = St$	one Chips	Operation	•				
D SC		S		Noise	•				
	$\overline{}$	$\top$		Clutch		_		/	
	(M)-		S SC	CV joints	•				
S SC (				Wheel bea	rings	<u> </u>			
33C H				Brakes					
			PT SC	Performan	ce	/			
			FISC	Hand brak	e	/			
SC	18			Tyres (lowest observed tread depth of tyres)					
				Left front	Left front 4.7 mm				
			S	Right front	Right front 5.3 mm				
	$\angle$			Left rear	Left rear 5.4 mm				
S D P S D					Right rear 5.3 mm				
Note: some defects	and blemishes may not be	e displayed in the diag	ıram	Spare	١	Yes			
Body Inspecti	on Comments			Suspensio	on				
•	os on windscreen			Suspensio	n performance	/			
Right wing mirro	or damaged			Steering p	erformance	/			
				Shock abso	orbers				
Conditions Dur	ring Body Inspection		Dry	Air Condit	Air Conditioning / Heater				
Under Carriag	e and Under Bonne	t Inspection Com	ments	Operation	Operation				
Front wheel driv	/e			Electrical	/ Accessories				
Oil leak Transmission le	ak			Head light	s	/			
Transmission ie	ak			Tail lights	•	/			
Interior Comm	nents			Indicators		/			
Seats:	Good			Dashboard	l warning lights	/			
Carpets:	Good			Wipers (fro	ont & rear)				
Panels:	Good			Window w	inder FL •	/			
Dashboard:	Good	Window w	inder FR •	/					
General Comm	nents		Window w	inder RL •	/				
Due for service	since 23/10/25/ only	water in coolant re	eservoir	Window w	inder RR				
Can't use A/C b	ecause ac fan speed	button missing		Rear view	mirrors				
Road Conditions During Test Drive Dry									
Engine Timing		Timing Chain		CD (basic test only)  Number of keys  1					
			No Kms	Central loc	,	· •			
Inspected by:	Cameron Senior-			Remote lo					
Published by:					asic test only)			1	
Published by: Janine Bell					usic test offiy)	$\dashv$			

I have read and understood this condition guide:

Inspection Date: 30 Dec 2025

NAME

SIGNATURE

Reversing camera