

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,888,403 | Version: | 1 |
| Created: | 31 Dec 2025 | | |


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Nissan | Model: | Leaf |
| Body Style: | Hatchback | Year: | 2015 |
| Rego No.: | NCY623 | Rego Expiry: | 04 Jun 2026 |
| WoF Expiry: | 22 May 2026 | Odometer: | 53,585 Kms |
| Good No.: | 27888403 | VIN: | 7AT0DH8KX20122268 |
| Next Service: | | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments**Interior Comments**

| | |
|------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |

General Comments

| | | | |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry | | |
| Engine Timing Mechanism | Unknown | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by: | Sione Mae | | |
| Published by: | Sione Mae | | |
| Inspection Date: | 31 Dec 2025 | | |

OK Requires Attention N/A

Engine

| | | | |
|---------------------------|---|--|---|
| Oil level | | | ✓ |
| Smoke & fumes | | | ✓ |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |

Transmission

| | | | |
|----------------|---|--|---|
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |

Brakes

| | | | |
|-------------|---|--|--|
| Performance | ✓ | | |
| Hand brake | ✓ | | |

Tyres (lowest observed tread depth of tyres)

| | | | |
|-------------|------|--|--|
| Left front | 6 mm | | |
| Right front | 3 mm | | |
| Left rear | 5 mm | | |
| Right rear | 5 mm | | |
| Spare | N/A | | |

Suspension

| | | | |
|------------------------|---|--|--|
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |

Air Conditioning / Heater

| | | | |
|-----------|---|--|--|
| Operation | ✓ | | |
|-----------|---|--|--|

Electrical / Accessories

| | | | |
|-----------------------------|---|--|---|
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____