

Basic Condition Guide

•	Report ID:	port ID: 27,889,613		1	
	Created:	02 Jan 2026			

	urnei	S Basi	c Condition Guide	Created: 02 Jan 2026			
			Τ			Doguiros	
Make:	Holden	Model:	Colorado	- OK		Requires Attention	N/A
Body Style:	Utility	Year:	2015	Engine			
Rego No.:	RAK876	Rego Expiry:	08 Jan 2026	Oil level			
WoF Expiry:	09 Jan 2026	Odometer:	164,208 Kms	Smoke & fumes	V		
Good No.:	27889613	VIN:	MMU148MK0GH622333	Engine performance	~		
Next Service:	no sticker	Service History:	No	Noise	V		
lote: This report i	•	do for ago and mileago Pr	Coolant condition	~			
iagnostic testing u	e only. Consideration is mad indertaken. The vehicle has dection prior to purchase a	been driven up to 50km/l	Cooling performance	~			
			or arradutional charge.	Radiator / Hoses (visual)	1		
(ey 5 = Scratch F	R = Rust C = 0	Crack *= Deca	ls W = Significant scuffs	Transmission			
S = Scratch $R = Rust$ $C = Crack$ *= Decals $W = Significant scuffs$ D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation	V		
				Noise	1		
S SC S P SC W W D W				Clutch			1
				CV joints	1		
			S	Wheel bearings	1		
				Brakes			
	119/			Performance	V		
			R	Hand brake	1		
S R SC	HO			Tyres (lowest observed tread depth of tyres)			
	JIB OF			Left front			5 mm
			S	Right front			5 mm
				Left rear			5 mm
DRW	W	S P S C	W DSC W	Right rear			9 mm
latai sama dafast	s and blemishes may not b	a displayed in the diagra		Spare	Yes		
	ion Comments	e dispiayed in the diagra		Suspension	1.00		
body mspece				Suspension performance	V		
				Steering performance	V		
				Shock absorbers	1		
Conditions Du	uring Body Inspection		Dry	Air Conditioning / Heater			
	ge and Under Bonne	t Inspection Comm		Operation	V	<u> </u>	l l
Underbody oxi	<u> </u>	emspection comm	icitis —	Electrical / Accessories			
oao	adiio			Head lights	V		
				Tail lights	V		
Interior Com	ments		Indicators	V			
Interior Comments Seats: Average				Dashboard warning lights	V		
				Wipers (front & rear)	1		
Carpets: Panels:	Average Average			Window winder FL	1		
Dashboard: Average			Window winder FR	V			
	_			1			
General Com	ments		Window winder RL	_			
				Window winder RR	<i>'</i>		
				Rear view mirrors	/		
		I_		Radio (basic test only)	/		<u> </u>

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 02 Jan 2026

Sione Mae

Sione Mae

Engine Timing Mechanism

Inspected by:

Published by:

Dry

Timing Chain

Yes

NAME			

No

SIGNATURE			

2

1

1

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms