

| Report ID: | 27,889,737 | Version: | 2 |
|------------|-------------|----------|---|
| Created: | 31 Dec 2025 | | |

OK

1

1 1 Requires Attention

N/A

| FAT. | 1000 | Poo | ic Condition Guide | Report ID: 27,889,7 |
|-----------------------|-----------------------------------|------------------------|--|-------------------------|
| | nue | <u> </u> | | Created: 31 Dec 2 |
| Make: | Audi | Model: | A3 | |
| Body Style: | Hatchback | Year: | 2011 | Engine |
| Rego No.: | MWL770 | Rego Expiry: | 11 Jan 2026 | Oil level |
| WoF Expiry: | 01 Dec 2026 | Odometer: | 171,928 Kms | |
| Good No.: | 27889737 | VIN: | WAUZZZ8P8BA098255 | Smoke & fumes |
| Next Service: | 170,000kms | Service History: | No | Engine performance |
| ote: This report is | | | | Noise |
| his report is a guide | only. Consideration is made | | arts have not been dismantled or h from cold. The Vendor recommends a | Coolant condition |
| | ection prior to purchase an | | | Cooling performance |
| (ey | | | | Radiator / Hoses (visua |
| = Scratch R | = Rust $C = C$ | rack *= Deca | als W = Significant scuffs | Transmission |
| D = Dent P | T = Paint defect P = Paint defect | in dent SC = Sto | ne Chips | Operation |
| sc | | PSC | | Noise |
| | | | | Clutch |
| | | | S | CV joints |
| | MA UT | | | Wheel bearings |
| SC 6 | | | | Brakes |
| | MC 11. | | | Performance |
| | | | | Hand brake |
| SC | TR - | | | Tyres (lowest observe |
| | | | | Left front |
| | | | (Q) | Right front |
| | | | | Left rear |
| | | | | Right rear |
| lote: some defects | and blemishes may not be | displayed in the diagr | am | Spare |
| | ion Comments | | | Suspension |
| | | | | Suspension performa |
| | | | | Steering performance |
| | | | | Shock absorbers |
| Conditions Du | ring Body Inspection | | Dry | Air Conditioning / Ho |
| | ge and Under Bonnet | Inspection Comn | nents | Operation |
| | n engine & transmissi | | | Electrical / Accessori |
| | - | | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Good | |
| General Comments | | |

Service overdue.

Rumble on road, possibly wheel bearing or tyres, suggest further investigation. 2WD petrol auto turbo hatch.

| Road Conditions During Test Drive | | Wet |
|-----------------------------------|--------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Daryll Timms | |
| Published by: | Daryll Timms | |
| Inspection Date: | 31 Dec 2025 | |

| I have read and understood |
|----------------------------|
| this condition guide: |

| NAME | | | |
|------|--|--|--|

| Cooling performance | / | | |
|------------------------------|-------------------|--------|----------|
| Radiator / Hoses (visual) | / | | |
| Transmission | | | • |
| Operation | V | | |
| Noise | V | | |
| Clutch | | | 1 |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | ' | | |
| Hand brake | / | | |
| Tyres (lowest observed tread | depth of | tyres) | |
| Left front | | | 5 mm |
| Right front | | | 4 mm |
| Left rear | | | 4 mm |
| Right rear | | | 4 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | ' | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | / | | |
| Dashboard warning lights | \(\frac{1}{V} \) | | |
| Wipers (front & rear) | / | | |
| Window winder FL | ' | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | ' | | |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | V |
| | | | |