


Make:	Ssangyong	Model:	Rexton
Body Style:	SUV	Year:	2016
Rego No.:	KEZ428	Rego Expiry:	23 Nov 2026
WoF Expiry:	25 Nov 2026	Odometer:	181,410 Kms
Good No.:	27890210	VIN:	KPTH0C1FSGP361276
Next Service:	186604	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Large Stone Chips Windscreen

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Rear Bump Stops Perished

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Conditions During Test Drive	Dry				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Darren Beban				
Published by:	James Scott				
Inspection Date:	09 Jan 2026				

I have read and understood
this condition guide:

NAME

SIGNATURE