


Make:	Ford	Model:	Escape
Body Style:	SUV	Year:	2002
Rego No.:	JZY112	Rego Expiry:	01 Apr 2026
WoF Expiry:	23 Dec 2026	Odometer:	188,976 Kms
Good No.:	27890657	VIN:	JC0YU041321105351
Next Service:	?	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Crack in middle bottom edge of windscreen. Small stone crack in left side of windscreen. Left side of grille is broken. Left edge broken off stone guard on front of bonnet.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Oil leak from engine.

**Interior Comments**

Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Good

**General Comments**

Radio/cd player are not working. Small hole & vinyl seat covering is cracking & lifting off base of driver's seat. Right rear door frame seal is damaged & torn. Key remote is not working.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Jason Young
Published by:	Nick Beaton
Inspection Date:	06 Jan 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,890,657	Version:	1
Created:	06 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	7.0	mm	
Right front	7.0	mm	
Left rear	6.6	mm	
Right rear	6.6	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_