


Make:	Ssangyong	Model:	Tivoli
Body Style:	SUV	Year:	2016
Rego No.:	RNR359	Rego Expiry:	15 Oct 2026
WoF Expiry:	21 Jan 2027	Odometer:	66,929 Kms
Good No.:	27892292	VIN:	KPT30B1VSFP042078
Next Service:	76930	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	RF seat base vinyl cracked ,
--------	------------------------------

Carpets:	Average
----------	---------

Panels:	Average
---------	---------

Dashboard:	Average
------------	---------

**General Comments**

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Unknown
-------------------------	---------

Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
----------------------------------	------------------------------	-----------------------------	-----

Inspected by:	Donovan Matara
---------------	----------------

Published by:	Janine Bell
---------------	-------------

Inspection Date:	05 Jan 2026
------------------	-------------

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,892,292	Version:	1
Created:	28 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	5.4 mm		
Right front	5.6 mm		
Left rear	4.2 mm		
Right rear	6.3 mm		
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE \_\_\_\_\_