


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Suzuki      | Model:           | Grand Vitara      |
| Body Style:   | SUV         | Year:            | 2003              |
| Rego No.:     | DQP777      | Rego Expiry:     | 21 Jul 2026       |
| WoF Expiry:   | 24 Sep 2026 | Odometer:        | 153,077 Kms       |
| Good No.:     | 27894361    | VIN:             | JSAFTA03V00200881 |
| Next Service: | 161800      | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch      R = Rust      C = Crack      \* = Decals      W = Significant scuffs  
D = Dent      PT = Paint defect      P = Pin dent      SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection Dry

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

## General Comments

## Oil seepage

|                                   |                          |     |                          |    |     |
|-----------------------------------|--------------------------|-----|--------------------------|----|-----|
| Road Conditions During Test Drive | Dry                      |     |                          |    |     |
| Engine Timing Mechanism           | Timing Chain             |     |                          |    |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> | Yes | <input type="checkbox"/> | No | Kms |
| Inspected by:                     | Alana Saunders           |     |                          |    |     |
| Published by:                     | Alana Saunders           |     |                          |    |     |
| Inspection Date:                  | 06 Jan 2026              |     |                          |    |     |

I have read and understood  
this condition guide:

**NAME**

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,894,361  | Version: | 1 |
| Created:   | 06 Jan 2026 |          |   |

|   | OK  | Requires Attention | N/A |
|---|-----|--------------------|-----|
| <b>Engine</b>                                       |     |                    |     |
| Oil level   | ✓   |                    |     |
| Smoke & fumes                                       | ✓   |                    |     |
| Engine performance                                  | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Coolant condition                                   | ✓   |                    |     |
| Cooling performance                                 | ✓   |                    |     |
| Radiator / Hoses (visual)                           | ✓   |                    |     |
| <b>Transmission</b>                                 |     |                    |     |
| Operation   | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Clutch  | ✓   |                    |     |
| CV joints   | ✓   |                    |     |
| Wheel bearings                                      | ✓   |                    |     |
| <b>Brakes</b>                                       |     |                    |     |
| Performance   | ✓   |                    |     |
| Hand brake  | ✓   |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |     |                    |     |
| Left front  |     | 6.5 mm             |     |
| Right front   |     | 7 mm               |     |
| Left rear   |     | 6.5 mm             |     |
| Right rear  |     | 6.5 mm             |     |
| Spare   | Yes |                    |     |
| <b>Suspension</b>                                   |     |                    |     |
| Suspension performance                              | ✓   |                    |     |
| Steering performance                                | ✓   |                    |     |
| Shock absorbers                                     | ✓   |                    |     |
| <b>Air Conditioning / Heater</b>                    |     |                    |     |
| Operation   | ✓   |                    |     |
| <b>Electrical / Accessories</b>                     |     |                    |     |
| Head lights   | ✓   |                    |     |
| Tail lights   | ✓   |                    |     |
| Indicators  | ✓   |                    |     |
| Dashboard warning lights                            | ✓   |                    |     |
| Wipers (front & rear)                               | ✓   |                    |     |
| Window winder FL                                    | ✓   |                    |     |
| Window winder FR                                    | ✓   |                    |     |
| Window winder RL                                    |     |                    | ✓   |
| Window winder RR                                    |     |                    | ✓   |
| Rear view mirrors                                   | ✓   |                    |     |
| Radio (basic test only)                             | ✓   |                    |     |
| CD (basic test only)                                |     |                    | ✓   |
| Number of keys                                      | 2   |                    |     |
| Central locking                                     | ✓   |                    |     |
| Remote locking                                      |     |                    | ✓   |
| Sat. nav. (basic test only)                         |     |                    | ✓   |
| Reversing camera                                    |     |                    | ✓   |

**SIGNATURE**