

Report ID:	27,896,476	Version:	1
Created:	06 Jan 2026		


Make:	Daihatsu	Model:	Sirion
Body Style:	Hatchback	Year:	2004
Rego No.:	CGU248	Rego Expiry:	10 Feb 2026
WoF Expiry:	01 Aug 2026	Odometer:	190,166 Kms
Good No.:	27896476	VIN:	JDAM101S000516601
Next Service:	197,669 Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Crack in front windscreen  
Right rear taillight has had crack in lens repaired

Conditions During Body Inspection	Dry
-----------------------------------	-----

## Under Carriage and Under Bonnet Inspection Comments

2WD  
Surface rust on underside of vehicle  
Exhaust snapped off from rear muffler back (sitting in boot)

## Interior Comments

Seats:	Stains
Carpets:	Wear on drivers side
Panels:	Good
Dashboard:	Good

## General Comments

Radio isn't working  
Vehicle getting hard to start, possible starter motor starting to wear out, advise to have checked

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Hoani Saunders
Published by:	Robert Chardon
Inspection Date:	06 Jan 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4.1 mm
Right front			2.4 mm
Left rear			4.0 mm
Right rear			3.7 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_