


Make:	Mazda	Model:	Demio
Body Style:	Hatchback	Year:	2012
Rego No.:	LCP621	Rego Expiry:	05 Apr 2026
WoF Expiry:	06 Oct 2026	Odometer:	245,066 Kms
Good No.:	27897093	VIN:	7AT0C12HX17530179
Next Service:	250,500Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch      R = Rust      C = Crack      \* = Decals      W = Significant scuffs  
D = Dent      PT = Paint defect      P = Pin dent      SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

- LH wing mirror cover missing
- RH wing mirror cover crack
- LH sill damage
- Rear bumper insecure

## Conditions During Body Inspection

- Under Carriage and Under Bonnet
- RF engine mount worn out
- Brake fluid bottle cap missing
- Window washer bottle cap missing

### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

## General Comments

Both side wing mirror cannot adjust  
Remote key fob missing

Road Conditions During Test Drive	Dry				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Bobby Zhong				
Published by:	Bobby Zhong				
Inspection Date:	13 Jan 2026				

I have read and understood  
this condition guide:

**NAME**

Report ID:	27,897,093	Version:	1
Created:	13 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		6 mm	
Right front		6 mm	
Left rear		7 mm	
Right rear		5 mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

**SIGNATURE**