

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,899,144  | Version: | 3 |
| Created:   | 27 Jan 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Nissan      | Model:           | March             |
| Body Style:   | Hatchback   | Year:            | 2015              |
| Rego No.:     | NDQ862      | Rego Expiry:     | 15 May 2026       |
| WoF Expiry:   | 27 Jan 2027 | Odometer:        | 76,424 Kms        |
| Good No.:     | 27899144    | VIN:             | 7AT0DH0KX20054679 |
| Next Service: | 86000       | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection    Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

## General Comments

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Greg Morgan                  |                             |     |
| Published by:                     | Michael Little               |                             |     |
| Inspection Date:                  | 07 Jan 2026                  |                             |     |

OK    Requires Attention    N/A

| Engine                                       |        |  |   |
|--|--------|--|---|
| Oil level                                    | ✓      |  |   |
| Smoke & fumes                                | ✓      |  |   |
| Engine performance                           | ✓      |  |   |
| Noise  | ✓      |  |   |
| Coolant condition                            | ✓      |  |   |
| Cooling performance                          | ✓      |  |   |
| Radiator / Hoses (visual)                    | ✓      |  |   |
| Transmission                                 |        |  |   |
| Operation                                    | ✓      |  |   |
| Noise  | ✓      |  |   |
| Clutch                                       |        |  | ✓ |
| CV joints                                    | ✓      |  |   |
| Wheel bearings                               | ✓      |  |   |
| Brakes                                       |        |  |   |
| Performance                                  | ✓      |  |   |
| Hand brake                                   | ✓      |  |   |
| Tyres (lowest observed tread depth of tyres) |        |  |   |
| Left front                                   | 3.0 mm |  |   |
| Right front                                  | 3.0 mm |  |   |
| Left rear                                    | 3.0 mm |  |   |
| Right rear                                   | 3.0 mm |  |   |
| Spare  | Yes    |  |   |
| Suspension                                   |        |  |   |
| Suspension performance                       | ✓      |  |   |
| Steering performance                         | ✓      |  |   |
| Shock absorbers                              | ✓      |  |   |
| Air Conditioning / Heater                    |        |  |   |
| Operation                                    | ✓      |  |   |
| Electrical / Accessories                     |        |  |   |
| Head lights                                  | ✓      |  |   |
| Tail lights                                  | ✓      |  |   |
| Indicators                                   | ✓      |  |   |
| Dashboard warning lights                     | ✓      |  |   |
| Wipers (front & rear)                        | ✓      |  |   |
| Window winder FL                             | ✓      |  |   |
| Window winder FR                             | ✓      |  |   |
| Window winder RL                             | ✓      |  |   |
| Window winder RR                             | ✓      |  |   |
| Rear view mirrors                            | ✓      |  |   |
| Radio (basic test only)                      | ✓      |  |   |
| CD (basic test only)                         |        |  | ✓ |
| Number of keys                               | 1      |  |   |
| Central locking                              | ✓      |  |   |
| Remote locking                               | ✓      |  |   |
| Sat. nav. (basic test only)                  |        |  | ✓ |
| Reversing camera                             | ✓      |  |   |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_