


Make:	Isuzu	Model:	D-MAX
Body Style:	Utility	Year:	2015
Rego No.:	HYY360	Rego Expiry:	26 Feb 2026
WoF Expiry:	12 Mar 2026	Odometer:	299,259 Kms
Good No.:	27899710	VIN:	MPATFS85JFT009083
Next Service:	308000	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch      R = Rust      C = Crack      \* = Decals      W = Significant scuffs  
D = Dent      PT = Paint defect      P = Pin dent      SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

- Front bumper insecure
- Right C pillar damage by vent
- Scratches and scuffs on tool boxes
- Minor sill dents

## Conditions During Body Inspection

### Under Carriage and Under Bonnet Inspection Comments

Front pads, rear shoes worn

## Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

## General Comments

- Left front rattle
- Gear selector worn
- Ac fan not working
- Suspension rattles and squeaks

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Greg Morgan		
Published by:	Sean Butcher		
Inspection Date:	07 Jan 2026		

I have read and understood  
this condition guide:

**NAME**

Report ID:	27,899,710	Version:	1
Created:	10 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation		✓	
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance		✓	
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		8.0 mm	
Right front		8.0 mm	
Left rear		8.0 mm	
Right rear		8.0 mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance		✓	
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

**SIGNATURE**