

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,903,804 | Version: | 1 |
| Created: | 10 Jan 2026 | | |


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | BMW | Model: | 740i |
| Body Style: | Sedan | Year: | 1997 |
| Rego No.: | BAA447 | Rego Expiry: | 16 Jan 2026 |
| WoF Expiry: | 09 Mar 2026 | Odometer: | 159,035 Kms |
| Good No.: | 27903804 | VIN: | WBAGJ82000DB29534 |
| Next Service: | no sticker | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Right headlight cracked
Weak boot and bonnet struts
Dents on both sills

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Underbody surface rust
Engine oil leak

Interior Comments

Seats: worn
Carpets: Average
Panels: Average
Dashboard: Poor

General Comments

Handbrake release lever broken
Suspected engine misfire, requires further investigation
Noisy drive belts

| | | | |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry | | |
| Engine Timing Mechanism | Timing Chain | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by: | Sione Mae | | |
| Published by: | Sione Mae | | |
| Inspection Date: | 10 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|----|--------------------|------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | | ✓ | |
| Noise | | ✓ | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 5 mm |
| Right front | | | 5 mm |
| Left rear | | | 4 mm |
| Right rear | | | 4 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | | ✓ | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | | ✓ | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____