


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Subaru | Model: | Impreza |
| Body Style: | Wagon | Year: | 2011 |
| Rego No.: | JJJ616 | Rego Expiry: | 17 Mar 2026 |
| WoF Expiry: | 31 Jan 2026 | Odometer: | 136,406 Kms |
| Good No.: | 27906353 | VIN: | 7AT0GF09X15046219 |
| Next Service: | 145,000 | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

| | |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

Under Carriage and Under Bonnet Inspection Comments

Oil level low + Oil leak.

Interior Comments

| | |
|------------|-----------------------------|
| Seats: | Average |
| Carpets: | drivers foot well mat worn. |
| Panels: | Average |
| Dashboard: | Average |

General Comments

Left sun visor broken. AC pump noisy & not blowing cold. Radio not responding.
 Vibration when braking.

| | |
|-----------------------------------|---|
| Road Conditions During Test Drive | Dry |
| Engine Timing Mechanism | Cambelt |
| Evidence of Cam Belt Replacement | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| | 101,500 Kms |
| Inspected by: | Finlay Lemmens |
| Published by: | Luke Saunders |
| Inspection Date: | 19 Jan 2026 |

I have read and understood
 this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,906,353 | Version: | 1 |
| Created: | 21 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | | ✓ | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | | ✓ | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 5.0 | mm | |
| Right front | 5.0 | mm | |
| Left rear | 7.0 | mm | |
| Right rear | 5.0 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | | ✓ | |
| CD (basic test only) | | | ✓ |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

SIGNATURE _____