


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Nissan | Model: | Qashqai |
| Body Style: | SUV | Year: | 2016 |
| Rego No.: | JRL461 | Rego Expiry: | 10 Dec 2026 |
| WoF Expiry: | 12 Mar 2026 | Odometer: | 166,824 Kms |
| Good No.: | 27914737 | VIN: | SJNFBAJ11A1548973 |
| Next Service: | 179,000 kms | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Tail gate strut weak, driver seat torn,

Conditions During Body Inspection

Wet

Under Carriage and Under Bonnet Inspection Comments
Interior Comments

Seats: Average

Carpets: Average

Panels: Good

Dashboard: Good

General Comments

Road Conditions During Test Drive

Wet

Engine Timing Mechanism

Timing Chain

Evidence of Cam Belt Replacement

Yes No

Kms

Inspected by: Marlon Espena

Published by: Marlon Espena

Inspection Date: 21 Jan 2026

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,914,737 | Version: | 1 |
| Created: | 21 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | | ✓ | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | 6 mm | |
| Right front | | 6 mm | |
| Left rear | | 6 mm | |
| Right rear | | 6 mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____