


Make:	Volkswagen	Model:	T5
Body Style:	Van	Year:	2007
Rego No.:	EFU963	Rego Expiry:	16 Oct 2026
WoF Expiry:	05 Nov 2026	Odometer:	371,442 Kms
Good No.:	27914873	VIN:	WV2ZZZ7HZ8H012925
Next Service:	362,400kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch      R = Rust      C = Crack      \* = Decals      W = Significant scuffs  
D = Dent      PT = Paint defect      P = Pin dent      SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Right door check strap is broken. Left headlight service hole cover is missing (Dust and insects inside). Front bumper left blank cover is missing.  
Minor stone cracks in windshield.

Conditions During Body Inspection	Dry
-----------------------------------	-----

### Under Carriage and Under Bonnet Inspection Comments

Oil level sensor is not connected. Leaking from engine.

### Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

## General Comments

Oil service is overdue. Clutch meet point is high. ESP is not operating. Speed cluster cover is cracked. Sunglasses holder is broken (can not be closed).

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> No
Inspected by:	Yuki Itohara		
Published by:	Glen Charlton		
Inspection Date:	15 Jan 2026		

I have read and understood  
this condition guide:

**NAME**

Report ID:	27,914,873	Version:	1
Created:	15 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		8.0 mm	
Right front		8.0 mm	
Left rear		4.5 mm	
Right rear		6.0 mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

**SIGNATURE**