


|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,917,587  | Version: | 1 |
| Created:   | 16 Jan 2026 |          |   |

|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Holden      | Model:           | Commodore         |
| Body Style:   | Sedan       | Year:            | 2001              |
| Rego No.:     | ELT326      | Rego Expiry:     | 04 Oct 2026       |
| WoF Expiry:   | 10 Oct 2026 | Odometer:        | 191,771 Kms       |
| Good No.:     | 27917587    | VIN:             | 6H8VXK69F1L662998 |
| Next Service: | 200,970kms  | Service History: | No                |

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Both front back seat torn, interior r door panel torn, rear seat switch broken, tail light cracked, L rear window switch faulty, L rear c Pilar rust, engine and power steering leak,

Conditions During Body Inspection

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

|            |         |
|------------|---------|
| Seats:     | Poor    |
| Carpets:   | Poor    |
| Panels:    | Average |
| Dashboard: | Average |

### General Comments

R rear window faulty, driver seat torn, wing mirror adjuster faulty, aircon not cold, R front fog light cracked, transmission oil leak, bounce in the ramp,

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Marlon Espena                |                             |     |
| Published by:                     | Marlon Espena                |                             |     |
| Inspection Date:                  | 16 Jan 2026                  |                             |     |

|   | OK | Requires Attention | N/A  |
|---|----|--------------------|------|
| <b>Engine</b>                                       |    |                    |      |
| Oil level   |    | ✓                  |      |
| Smoke & fumes                                       | ✓  |                    |      |
| Engine performance                                  | ✓  |                    |      |
| Noise   | ✓  |                    |      |
| Coolant condition                                   |    | ✓                  |      |
| Cooling performance                                 | ✓  |                    |      |
| Radiator / Hoses (visual)                           | ✓  |                    |      |
| <b>Transmission</b>                                 |    |                    |      |
| Operation   | ✓  |                    |      |
| Noise   | ✓  |                    |      |
| Clutch  |    |                    | ✓    |
| CV joints   | ✓  |                    |      |
| Wheel bearings                                      | ✓  |                    |      |
| <b>Brakes</b>                                       |    |                    |      |
| Performance   | ✓  |                    |      |
| Hand brake  | ✓  |                    |      |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |      |
| Left front  |    |                    | 5 mm |
| Right front   |    |                    | 5 mm |
| Left rear   |    |                    | 6 mm |
| Right rear  |    |                    | 6 mm |
| Spare   |    | Yes                |      |
| <b>Suspension</b>                                   |    |                    |      |
| Suspension performance                              |    | ✓                  |      |
| Steering performance                                | ✓  |                    |      |
| Shock absorbers                                     | ✓  |                    |      |
| <b>Air Conditioning / Heater</b>                    |    |                    |      |
| Operation   |    | ✓                  |      |
| <b>Electrical / Accessories</b>                     |    |                    |      |
| Head lights   | ✓  |                    |      |
| Tail lights   | ✓  |                    |      |
| Indicators  | ✓  |                    |      |
| Dashboard warning lights                            | ✓  |                    |      |
| Wipers (front & rear)                               | ✓  |                    |      |
| Window winder FL                                    | ✓  |                    |      |
| Window winder FR                                    | ✓  |                    |      |
| Window winder RL                                    |    |                    | ✓    |
| Window winder RR                                    |    |                    | ✓    |
| Rear view mirrors                                   | ✓  |                    |      |
| Radio (basic test only)                             | ✓  |                    |      |
| CD (basic test only)                                |    | ✓                  |      |
| Number of keys                                      | 1  |                    |      |
| Central locking                                     |    | ✓                  |      |
| Remote locking                                      | ✓  |                    |      |
| Sat. nav. (basic test only)                         |    |                    | ✓    |
| Reversing camera                                    |    |                    | ✓    |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_